5. Private Claims

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

REMOUNATION CORMÉR

	*****	A 2000	
For corners IOSCO	Located In:	Corner Code #	
1. Public Land Survey	T 24N R 9E T R	G-11	
2. Property Controlling in Section	T R T R T R T R T R T R T R T R T R T R		
3. Miscellaneous Property in Sec.	$\frac{s}{s} = \frac{T}{T} = \frac{R}{R}$		
4. Lot No.	, Recorded Plat		

98-59


STATE OF KICHIGAN TOSCO COUNTY FILED

10 DEC 98 2:56 P.M.

BONITA M. COYLE REGISTER OF DEEDS

WILLIAM E. WOODS P.S., in a field survey on NOV 17, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Register of Deeds Stamp & File Number



NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration: 1958: R.J. COOKE VAN ETTAN CREEK ACRES NO. 1 LIBER 8 PG 35-36 1843; ORIGINAL GOVERNMENT NOTES

1959: R.J. COOKE MERKELVILLE NO. 2 LIBER 9 PG 15-16

1960: R.J. COOKE VAN ETTAN CREEK ACRES NO. 2 LIBER 9 PG 37-38

1962: R.J. COOKE VAN ETTAN CREEK ESTATES LIBER 10 PG 39-40

1974: R.L. MILLER BOUNDARY SURVEY LIBER 233 PG 865

1975: NORHTEAST LAND SURVEYS BOUNDARY SURVEY

1977: R.L. MILLER LCRC CONCRETE MONUMENT FD LIBER 77 PG 18

GOVERNMENT DID NOT SET THIS CORNER FROM SOUTH

THEY SET MEANDER CORNER AT 72.80 CHAINS AND

STOPPED GOVERNMENT SET THIS CORNER FROM WEST AT

80 CHAINS

SET POST

14" BIRCH N 60° W 21 LK.

10" BIRCH N 62° E 23 LK.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND CONCRETE MONUMENT & RECORDED WITTNESSES.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corne

CONCRETE MONUMENT

FND NAIL IN 14" BIRCH (DEAD) S15E 23.70

FND NAIL IN 12" BIRCH (DEAD) S26W 24.70

SET NAIL IN 14" RED FINE NO8E 36.65

SET NAIL IN 18" RED MAPLE SOUTH 29.71

SET NAIL IN 6" CEDAR N64W 26.33

SET NAIL IN 48" TWIN MAPLE S78E 31.74

ACCEPTED BY THE IOSCO COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 1990 AT A MEETING DN 9-22-98

Signed by WILLIAM E. WOODS P.S.

Surveyor's Michigan License No. 25882