MAR U 9 2000

13

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Filing	Requirement of A	ct 74, Mich. P.A	
or corners in				MICHIGAN
Iron	Located in	: Corn	er Code #	RECEIVED FOR RECORD
(County)				99 DEC 30 AMIO: 12
. Public Land Survey	T <u>43N</u> R <u>.</u> T <u>42N</u> R <u>.</u> T R_	32WI-	13	L.C. Recycle: L. 8, P. 22
. Property Controlling in Section 3. Miscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR	****		Register of Deeds Stamp & File Number
croperty in Sec.	· · · · · · · · · · · · · · · · · · ·			
ł. Lot No, Re	aardad Dlat			
5. Private Claims				- ABCDEFGHIJKLM
				2 - 5 - 4 - 3 - 2 - 1 - 1
Section Corner Sections 34 Section Corner Sections 3 a		V		3 9 10 11 12 -
, Gary L. Pisoni	in a field survey on	, 19	9 <u>99</u> do hereby st	ate 5
hat under requirements of n lines 1 and 2 above w	P.A. 74, Michigan P ere, in conformance	A. of 1970, the corn with regulations and	er points mention I rules therefore	as
equired in the current many	ual of survey instruct	ions of the United St	tates Department	of '
he Interior, Bureau of Land	Management or by a	decree of a Court of I	Law and /or that t	the 8 19 20 21 22 23- 24
corner points mentioned in the Michigan Board of Lan-	lines 3, 4 and 5 abov d Survevors or by a	Decree of a Court of	of Law; establish	ed.
e-established, monumented	l, recovered, <u>found</u> as	expressed below:		10 30 - 29 - 20 - 27 - 27 - 27 - 27 - 27 - 27 - 27
NOTE: Not more than 2 corn	ers, all in the same tow	n and range, may be re	corded	
NOTE: Not more than 2 corr on this certificate.	ers, all ill tite same tow	it and range, may be to		1231 -323334 35 36
A. Description of original r				
Original corner establish Original Corner: Cedar		16 by William A. Burt	, U.S. Deputy Su	rveyor. PEER GROUP APPROVED TRon Hay from 13-31-99
Original Bearing Trees: Yellov	v Pine 14"	N 59° E	14 lks (9.24	
Cedar	8"	N 25° W	6 lks (3.96	
On September 21, 184 Språd		S 49° E	26 lks (17.1	6 feet)
White	Birch 10"	S 12° W	16 lks (10.5	6 feet
A fence line runs West	from the corner posi-	tion and a fence line	runs North from	brass cap. No evidence of bearing trees. a point 5 feet East of the monument. Monument recorded in Liber 1, Page 7.
Black	Spruce 7"	S 11° E	12.7 feet	
Tama	rack 9"	\$ 39° W	25.2 feet	
B. Description of corner	evidence found and/o	r method applied in r	estoring or reesta	ablishing corner:
. No evidence of origi	nal B.T.s found.			
	he above described n	nonument and the following S 07°E	llowing bearing tr 13.15 feet	rees:
Black Tamar	Spruce 12" ack 14"	\$ 41° W	25.36 feet	·
	monument as the bes	t available evidence f	for restoring the c	corner position.
Corner record resea	rch on file with Coun	ty Representative.		
Blazed and scribed	the following new be	aring trees: (all meas	urements taken t	cating the position of the corner: o a nail in side of tree)
Black Balsar	Spruce 8" n 8"	N 39°W N 26° E	19.61 feet 6.42 feet	THE OF MICHIGAR
	ກ c sign post	S 53° E	1.2 feet	GARY L.
99-22	D. A.	D-1-	2-28.99	PISONI **
Signed by Nacy de P	No. 97457	Date/		LAND Y MICHICAN STATEBOARD OF PROPERSIONAL SURVEYORS, JAN. 28, 1971
Surveyor's Michigan Licen	se No. <u>27457</u>		FORM APPROVED E	BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYSIS, JUN. 28, 1971 No. REVISED MAY 14,1975 REVISED JAN., 1983
		LIBER	8 page	27457 PENSED OCT., 1995