SURVEY & REMONUMENTATION

H.C. Milker

Stock No. 26273

MAR 1 9 1997 COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 For corners in IRON COUNTY Corner Code # Located In: Iron 95 DEC 23 AM 9: 15 1/42N R488W 1 1. Public Land Survey <u>42N</u> R<u>32W</u> 2. Property Controlling in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. _, Recorded Plat 5. Private Claims S.19, T42N R32W Section Corner S.24, T42N R33W, S.30, T42N R32W S.25, T42N R33W, , in a field survey on <u>November 20, 19 96</u> do hereby state <u>Garv L. Pisoni</u> that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original corner established by Austin Burt, U.S. Deputy Surveyor in 1847. Original corner: Wood Post Original bearing trees: 65 links (42.90 feet) 10" S 51° W Sugar 60 links (39.60 feet) N 43° E ጸ" Sugar Original Subdivison established by Zelotes B. Searls in 1849. Original bearing tree: 35 links (23.10 feet) S 30° E 10" Sugar Maple Description of corner evidence found and/or method applied in restoring or reestablishing corner: No original corner evidence found. Accept the intersection of a North-South wire fence line and a rock fence line running East as PEER GROUP APPROVED the best available evidence for restoring the corner position. REPRESENTATIVE Corner Record Research on file with County Representative. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C. At the corner position, I set a 3/4" outside diameter by 3 feet long aluminum rod monument with a 3" cast aluminum cap, stamped to read: Iron County Remonumentation, T42N, R33W, R32W, S-24, S-19, S-25, S-30, 1996, RLS-27457 from which I established the following new bazed and scribed bearing trees: (all measurements taken to a nail in side of tree) TATE OF MICHIGA N 12° W 19.33 feet Sugar Maple 6" 8" N 55° E 21.73 feet Black Cherry GARY L. 27.99 feet S 05° E 5/8" x 30" Rebar **PISONI** 92.94 feet S 83° W Sugar Maple 7" LAND 0.41 feet 61 Steel Sign Post SURVEYOR No. 27457 ERED LAND CO LAND

Signed by . 27457 Surveyor's Michigan License No.

#96-54

PPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995