	LAND COR	NER RECORDATION CERTIFIC	CATE	
		nt of Act 74, Mich. P.A. 1970 as		
For corners in		ı		
Iron	Located In:	Corner Code #		
(County)				
1. Public Land Survey	T <u>42N</u> R <u>35M</u> TR	A7		
	TR	<u></u>		
2. Property Controlling	S 20 T 42N R 35N	12		
in Section	S R			
3. Miscellaneous	S R	S T R Register of Deeds Stamp & File Number		
Property in Sec.	5 I K	des de la company de la compan		
4. Lot No, Reco	rded Plat		A B C D E F G H I J K L	
5. Private Claims	12 May 17	7. 2004	2 - 5 - 5 - 4 - 3 - 1 - 2 - 1 - 1	
	A7 May 10		3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
I, Stephan J. Szyszkoski	•	, 20 do hereby state	4 - 7 - 6 - 9 - 10 - 11 - 12	
that under requirements of P.A. 7	74, Michigan P.A. of 1970, the	corner points mentioned in lines 1 and 2		
above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in				
conformance with the rules of th established, re-established, monu	e Michigan Board of Land Surv	eyors or by a Decree of a Court of Law;		
established, re-established, mont	imented, recovered, round as e	expressed below.	9 10 30 29 28 27 26 25	
	rners, all in the same tow	n and range, may be recorded		
on this certificate.	**,		11 12 31 32 33 34 35 36	
A. Description of original mo	onument and accessories an	d/or subsequent restoration:		
(12-Sec. 20) Center-south 1/16	corner, Section 20. Not	ficate L10 P40, dated 12-21-02 by e established in the original survey	. Found no subsequent record.	
B. Description of corner evi	idence found and/or metho	d applied in restoring or reestablish	ning corner:	
visible; 8" Balsam S34E 9.6', sign post N45E 0.9'; Metal si corner. Cut down the Balsam 8 described below. (12-Sec. 20) Established the	scribing visible; 11" As gn post S55W 3.1'. Accept " S34E NBT to facilitate G corner on the North-South at index-corrected record	pen S74M 29.8', overgrown blazes; ed the monument as a careful and f PS observations. Left the monumen 1/4 line of Section 20, as run in distance of 20.00 chains south of	ring trees: 4" Balsam N72E 16.3', scribing 6" Aspen N15W 14.4', standing dead; Metal raithful perpetuation of the position of the it in place and made new witnesses as at the mean of the bearings of the East and the Center of Section 20. The distance fro	
(A7) Found 2" I.pipe with 3" b Set measuring nails in the fol bearing trees: 6" Balsam N16E 22.6' mrkd " 5" Balsam S64E 17.3' mrkd "	rass cap. (12) Set lowing new cap. Set 9" Sugar S18 NBT" 4" Sugar S19 NBT" 6" Sugar ces are to 7" Sugar Set sq'd	established to perpetuate locating of 1"ID I.pipe with 4" alum. MDNR measuring nails in: N34E 14.9' mrkd "1/16S BT" S70E 38.7' do S40M 25.3' do N85W 18.5' do cedar post adjacent. Bearings tic. Distances are to nail	STEPHAN J. SZYSZKOSKI LAND SURVEYOR No. 33986	