SURVEY & REMONUMENTATION

JAN 1 9 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in				
lron	Located In:	Corne	er Code #	IROH COUNTY
(County)				KAICUIE: O.M.
1. Public Land Survey	T_43N R_32W_	A-1	0	RECEIVED FOR RECORD
7. Fublic Edite Outvey	T_43N R_33W			00 pro 29 #M11: 24
	TR			98 DEC 28 Mill: 24 L.C. Records: L.7, P. 309
	T R			L.C. Records . L.
2. Property Controlling S_	TR	· ———		Land Jaker
in Section S_	<u>T R</u>			the second of the second
3. Miscellaneous S_	T R T R			Register of Deeds Stamp & File Number
Property in Sec. S_	\	· · · · · · · · · · · · · · · · · · ·		Trogister of occurs stating a raise stating a
4. Lot No, Records	ed Plat			-
5. Private Claims				
Quarter Corner Sec. 30, T43N, F	22214			2 6 7 5 4 3 7 2 1 1 1
Quarter Corner Sec. 25, T43N, I				3
				4 7 8 9 10 11 12
i, <u>Garv L. Pisoni</u> , in a	field survey on	<u>Dec. 14</u> , 19	98 do hereby	5
that under requirements of P.A.	7/1 Michigan P.A. of 1	1970 the corner	r points mentione	d 6 18 17 16 15 14 13
in lines 1 and 2 above were in	conformance with r	regulations and	rules therefore a	s 7
required in the current manual of	f survey instructions of	f the United Sta	ites Department o	of 8 19 20 21 22 23 24
the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the				e
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of)T -
the Michigan Board of Land Sur re-established, monumented, rece	veyors or by a Decre	e of a Court of	Law; established	
re-established, monumented, reco	overed, <u>Tourid</u> as expre	sseu Delow.		
NOTE: Not more than 2 corners, a on this certificate.	Il in the same town and r	range, may be rec	orded	12 -31 - 32 33 34 35 36
		andler subseque	nt rectoration:	
A. Description of original monu	ment and accessories	and/or subseque	an restoration.	
Original corner established o	n August 3, 1846 by /	Austin Burt, U.S	. Deputy Surveyo	r. Original Corner: Cedar Post
Original Bearing Trees:				
Cedar	16" \$ 43°		ks (5.28 feet) lks (16.5 feet)	
Lynn	12" N 08'	امستنفسالا عبالم	Pagourges restore	ed the corner position from a found P.K. nail in
of said highway. No evidence	of original corner or its	accessories. H	e accepted the P.	K. nail as the best available evidence of the
position of the original corner.	•			
1968 Bearing Trees:		4 T> N	55°E 81	.25 feet
Sugar Map	ble 8" (MDSH Re	- · · · · · · · · · · · · · · · · · · ·		5.80 feet
MBT Co. 1 MBT Co. 8	Felephone pole #2492	_		00 foot
I 1006 U.S. Highway No	. 2 was resurfaced and	d the above P.K.	, nail was replaced	d with a monument box and iron bar which was
set by the M.D.O.T.				
Set by wie ittimes		معرضا المسائمين	etoring or reestab	olishing corner: PEER GROUP APPROVED
B. Description of corner evide	ince found and/or meti	hod applied in re	storing or records	Tren A. Lucy 12-18-98
No evidence of original B.				COUNTY REPRESENTATIVE
No evidence of original of	1,5 (00.10.			hearing trees found.
Found the monument box	as described above wi	ith 1/2" pin in ce	enter of box. No	Dearing troop re-
Corner record research on f	IIG MICH COMM. Habita			ating the position of the corner:
C Description of monument	for corner and accesso	ories established	nument heing a	ating the position of the corner: 5/8" diameter by 30" long rebar, with a 3" V, R32W, R.M., 1/4, S-25, S-30, South, 42.86'
From the above describe	d corner position, I set	v Remonumenta	tion, T43N, R33V	V, R32W, R.M., 1/4, S-25, S-30, South, 42:50
aluminum cap stamped a	is tollows: Iron Count	ribed the followi	ing new bearing to	V, R32W, R.M., 1/4, S-25, S-30, South, 42.86' rees: (All measurements taken to a nail in side of
1998, RLS 27457, from	MINOR I MINES AND ALL		93.93 fee	MANAGE MICH
tree) Sugar Ma	aple 20"	N 56°W	42.86 fee	
R,M.	5/8" x 30" rebar	North	86.56 fee	
Sugar Ma	aple 7"	N 52°E S 34°W	71.18 fee	at 選集 PISONL [1]
Sugar Ma	apie 11"	North	43.63 fee	et LAND
Steel sig	n post			No. 101
98-102 May 1 fr	j Latera	_ Date	-21-98	27/457 2000 STREET SAN 28, 1971
Sidned by		_	FORM APPROVED	TO AN CTATE BOARD OF PROFESSIONAL SURVEY OF AN 4075
Surveyor's Michigan License	No27457			EV MICHIGAN STATE OF THE PROPERTY IN 1983
·				" " 馬斯爾斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯斯