LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF -:	LOCATED IN -:	CORNER CODE NUMBER	
1. PUBLIC LAND SURVEY	_ T N. R E. W.		
2. PROPERTY CONTROLL- 17 ING IN SECTION————————————————————————————————————	,T. 43 N. R. 33 W.	17-12	
3. MISCELLANEOUS PROPERTY IN SECTION			-
4. LOT NO , RECO	ORDED PLAT		
5. PRIVATE CLAIMS			REGISTER OF DEEDS STAMP AND FILING NUMBER
, Arthur O. Enger	do haraby o	partify that under requirements of	f P.A. 74, Michigan P.A. of 1970,
re-established, monumented, re-nand rules therefore as required in Bureau of Land Management or land 5 above were, in a field surve as expressed below and in confor Decree of a Court of law: A. Description of original monumer Corner 17-12 (South	nonumented, recovered or real the current manual of survey and decree of a court of law by on	estored as expressed below and ey instructions of the United Str. Furthermore, that the corner, 19, found, recovered, rest Michigan State Board of Registr subsequent restoration: 5 1/4 line of Sec. 17, Found a tack in a picedly set by W. E. DeWa	ne slab hub stake
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner: It appears that this corner was set by measuring on a compass North bearing 1323.5 feet from a monument at the 1/4 cor. bet. Sec. 17 & 20, then on a compass East (or 90° angle) bearing 1322.6 ft. and setting a point for the center of the SE4, then on a S'ly bearing 1323.4 ft. to a monument previously established for the E 1/16 cor. bet. Sec. 17 & 20, thus establishing lines purporting to be the boundaries of Govt. Lot 2. (How the distances were determined I do not know). Since the North and East quarter-sections were apparently lost prior to 1940, it is unlikely a bona fide section subdivision could be made and I found no evidence of any such subdivision, having to reestablish these missing corners myself before I could make a correct subdivision. That survey determined that the true point for the subject corner is N44° 17.8'W 18.24 ft. from this one. However not desiring to unsettle the model and because established the perpetual because the position of the corner:			
C. Replaced the tack in pine slab with a 1" I.D. x 36" iron pipe with 3½" aluminum cap. Black Spruce 5 S89°W (mag.) 23.1 ft. "1/16S, BT" Black Spruce 8 N83°E (mag.) 22.0 ft. "1/16S, BT"			
Black Spruce 8	моз E (mag.) 22.0 f	t. "1/108, BT"	
SIGNED BY		DATE	
SURVEYOR'S MICHIGAN REG	SISTRATION NO		(SEAL)
FOR STATE AND UNITED ST	ATES AGENCIES:		must be the
SIGNED BY	CHIEF OF SURVEY PARTY	DATE	The state of the s
APPROVED AND SIGNED BY	11 11 4	DATEDATE	November 18, 1976
Arthur O. Enger Michigan Department of Natural Resources			
SURVEYOR'S MICHIGAN REGISTRATION NO. 13581			
FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971 REVISED MAY 14, 1973			