SURVEY & REMONUMENTATION

JAN 1 3 1998

SECTION

97-13a

Signed by

Surveyor's Michigan License No.____

27457

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

IROH COUNTY
PREMICAN
RECEIVED FOR RECORD

97 DEC 23 PM 1:30

THE CAND AND THE PERSON OF THE

For corners in Corner Code # Located in: Iron (County) T43N R 35W Public Land Survey 2. Property Controlling in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. __, Recorded Plat 4. Lot No. 5. Private Claims 2 Quarter Corner Between Sections 17 and 16, T43N, R35W 4 in a field survey on November 29 , 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 5 in lines 1 and 2 above were in conformance with regulations and rules therefore as 6 required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of 8 the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, 9 re-established, monumented, recovered, found as expressed below: 10 NOTE: Not more than 2 corners, all in the same town and range, may be recorded 1 on this certificate. 1: A. Description of original monument and accessories and/or subsequent restoration: Original corner established by Harvey Mellen in 1851, U.S. Deputy Surveyor. Original Corner: Wood Post Original Bearing Trees: 3 lks (1.98 feet) N 80° E White Pine 18" 24" N 40° W 5 lks (3.30 feet) White Pine On May 11, 1972, Donald D. Lappala, RLS with the U.S.F.S. restored the corner position at the intersection of a North and East fence line and set a 2 ½" dia. by 5' long galvanized iron pipe 24" above the ground surface with a 3" diameter brass capped stamped as follows: T43N, R35W, 1/4, S17, S16, 1972, RLS 12585, recorded in Land Corner Certificate Liber 3, Page 7 on July 17, 1972. 1972 Reference Objects: PEER GROUP APPROVED N 11° E 31.30 feet **Utility Pole** N481215 12-19-47 S 70° E 3.30 feet USFS Attention sign S 06° E 85.7 feet: Railroad crossing sign S 58° W 48.1 feet Railroad crossing sign Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original B.T.s found. On 11/29/97, found a U.S.F.S. brass capped pipe monument set by Donald D. Lappala RLS at the intersection of North and East fence lines along with the following reference objects: N 11° E 31.46 feet Utility Pole N 481215 S 70° E 3.30 feet: USFS Attention sign I accept the U.S.F.S. monument as the best available evidence for restoring the corner position. Corner record research on file with County Representative. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: From the above described monument, blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree): STATE OF MICHIGAN S 42° W 78.60 feet S 89° W 71.98 feet Tamarack 0.78 feet South Steel sign post ¥ **PISONI** FORM APPROVED BY MICHIGAN STATE BOARS OPPROFESSIONAN SHAVE 2745 THE VICTOR OF THE PROPERTY OF

_ Date _