

FEB 2 2 1996

COMMI	SSION
-------	-------

i							
LAND	CORNE	R RECO	RDATIC	IN CER	TIFIC	CATE	
Cilina.	Doguire	ement of	1 A at 7A	Mich	א מ	1070	
riiiligi	nedulit	sine (It O	MUL 14	. MICH.	г.н.	13/V	

IRON COUNTY RECEIVED FOR RECORD

93 DEC 29 PH 2: 22

REGISTER OF DEEDS

For corners in Iron Located In: Corner Code ## (County) 43N R 35W 1. Public Land Survey T 42N R 35W **Property Controlling** in Section Miscellaneous Property in Sec.

Register of Deeds Stamp & File Number

Đ

Lot No. _ , Recorded Plat

Private Claims _

Quarter Corner 36-1 T43-42N R35W

Gary L. Pisoni , in a field survey on . December 21 . 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, lound as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by John Burt, U.S. Deputy Surveyor on September 10, 1846.

Original corner: Sugar Post

Original bearing trees:

Elm Elm

20" 20 m N 48°E и 66°

11 links (7.26 feet)

10

11

12 13

41 links (27.06 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner or bearing tree remains. Corner position found marked by a drill rod with a punch mark inside of monument box. Corner located in centerline of 19th Street and on the West side of Lincoln Street. Quarter corner is part of the Assessor's Plat of Dober dating back to the 1930's.

This corner is accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above corner monument, I established the following new corner references: (all measurements taken to reference object or to a nail in side of Utility Pole)

ir eliferica careri c	0 101010000 00000	a, or cola marr	
Utility Pole	#18	N 54 E	40.39 feet
Telephone Pole	1900MBT	S 13°W	53.79 feet
Top Fire Hydra		ท 50 ^O พ	43.08 feet
Rebar	5/8"x30"	и 60 <mark>°</mark> Е	47.45 feet
Rebar	5/8"x30"	s 40°w	47.44 feet

ROYED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISEO JAN., 1943

OF: AF.

GARY L PISONI LAND SURVEYOR No.

TED LAND

Surveyor's Michigan License No. 27457