LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		rining naquirament of Act 74, when	
	Tron (County)	Located In:	Corner Code <i>⇒‡</i>
1.	Public Land Survey	T 44N R 31N	A5 .
		T R T R	B7
•	Brenady Castrolline	T R S T R	
₹.	Properly Controlling in Section	\$ T R	

Register of Deeds Stamp & File Number

____, Recorded Plat 4 Lot No

3. Miscellaneous

Property in Sec.

5. Private Claims __

....., in a field survey on ... do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:


NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A5			
Original monument and			
accessories not found.			

Original monument and accessories not found.

Original monument and accessories not found.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored midway and on line.

Restored midway and on line.

Restored pidway and on line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner A5 87

Set 1° ID x 32° IP w/4° aluginum cap. 5" maple \$11W 12.8' \$13 MBT 16" white pine M9N 46.6" x12 7" white pine M75W 72.1' s 12 Fence iron M76W 19.6'

Set 1" ID x 32" IP w/4" aluminum cap. 4" spruce \$24E 14.2" 1/4s NBT 10° balsam N97N 47.3 E/4s MBT

10" balsam M44W 39.4" 1/4s MBT

Set 1" ID x 32" IP w/4" atuminum cap. Corner falls in pond. 3" tamarack N70W 122.0' 1/16s BT marked incorrect 14" tamarack NO9E 173,5" 1/16s

Bī 3' tanarack post

1-19-89

Surveyor's Michigan License No. _