LAND CORNER RECORDATION CERTIFICATE

	Fili	ng Requirement of Ad	t 74, Mich. P.A. 19	970							
For comers in			1								
Iron	Located in:	Corner Code #									
(County)											
1. Public Land Survey	T 44K R T 44K R T R T R	31N H3	_								
Property Controlling in Section Miscellaneous Property in Sec.	S TR S TR S TR S TR			R	egiste	r of De	eds Si	amp &	File N	umbe	er
4. Lot No, Recor				, <u>, , , , , , , , , , , , , , , , , , </u>	вс	D E	F	5 H	1 J	κι	_
5. Private Claims	H3			1		_!_	_!_	Lļ_	_ [_	Щ,	
	ns Ma			3	Ĭ	ĺ	Ĭ.	<u> </u>	ĹĨ	أسل	Ĺ
L Stephan J. Szyszkoski	***	• • • • • • •			ŢŢ			L.I.		Ţ	2-
requirements of P.A. 74, Michiga	, in a med activey on ы P.A. of 1970, the com	oo 19 ner points mentioned in lines	1 and 2 above were in	1	íΠ	- i - T	j	Γĭ	Γï	Τi	•
conformance with regulations and	rules therefore as requir	red in the current menual of si	urvey instructions of the	5	1	11				\top	Π
United States Department of the that the corner points mentioned	interior, Bureau of Land I I in lines 3: 4 and 5 above	Menagement or by a decree of women and conformance with the	of a Court of Law and /or na rules of the Michigan	6	18	-17-	—16— 	15-	1 - -	┼ ╏	ე⊣
Board of Land Surveyors or by	a Decree of a Court	of Law; established, re-esta	iblished, monumented,	ןי ⊢	+-+	1-1					<u> </u>
recovered, found as expressed be	slow:			8	19	-20 	—21— 	22 	23- 	-2	
NOTE: Not more than 2 corr	ners, all in the same toy	en and range, may be reco	rded	9	╅╾┼	╌┼─┤	+-	╁┼┼	\vdash	+	_
on this certificate.				10	30	-2¦ 9	—2 ² 8	-27-	-26-	 -2	5-
		•		11	+		-	\vdash	 -	╅┈┨	_
				12	3¦1—∔	_32	3 <u>'</u> 3	<u></u> —3 <mark>+—</mark>	-3/5-	- −³	6-
				13							
A. Description of original mo 16) Quarter corner common to	section 13 T44M-R31	1N and Section 18 T44N~	R3OM. Corner reesta	blished	by si	ngle p	roport	ionate	Beasur	ement	:
n 1949 hv & O. Enger, RiS: '	'corper re-establishe	ed an line beetween sec	tion corners 39.945	chains	to nor	th and	to 50	uthC	orner		
noument 1° I D. v 36° iron a	nine with 4° aluminus	e cap. Witnesses to co	rner: B.Spruce 8 Nóó	E 25.5	lınks,	W. Spr	UCB 5	519W Y.	3 TIUK	5.	
13) Corner common to Section	ns 1-12 T44N-831W and	d Sections 6-7 T44M-R30	M. Corner remonumen	tea in	1768 6	IУ П.U.	Enger Lundau	, KLJ:	Mitae	erae	

replaced from stumps of two white pines believed to be original BT's...Corner monument: 1° iron pipe with 4° to corner: White Pine 12 S19E 23.5 links, White Pine 12 S39W 71.5 links.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.
- (M6) Found Enger's monument in good condition, as described, a 1" I.D. iron pipe capped with a 4" cast aluminum MDMR tablet, at record bearing and distance from the remains of the 1969 bearing trees. Both were recovered as rotting stumps. My measurements from the monument to adjacent section corners are 2633.42' M. and 2639.5' S. The monument was found 1.7' west of a straight line between these corners. I accepted the monument as a careful and faithful reestablishment of the position of the original corner. Left the monument in place and marked 4 new mitnesses as described below. Corner recovered and remitnessed by D.Lampela and B.Wheeler, Baraga District Office, MDNR.
- (M3) Recovered the 1968 monument, as described, in good condition, and at record bearing and distance from the 1968 mitnesses, both in good condition. Left the monument in place and marked three new accessories as described below. Corner rewitnessed by D.Lampela and B.Wheeler, Baraga District Office, MDNR.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner (M6) Found 1 pipe with 4 MDMR cap. (M3) Found 1 pipe with 4 MDMR cap. OF MIC Blazed and scribed the following: Blazed and scribed the following: "SI NOT" 4" Maple N36N 24.4" 18" W. Pine N86E 78.9" "1/45 NBT" 8" Maple N81E 16.0' "\$6 NBT" STEPHAN J 4" Spruce N74E 35.2' 1/4S NOT \mbox{B}^{*} Squared cherry \$63E 1.2' to notch SZYSZKOSKI 20" W. Pine M20W 71.5' "1/45 N8T" The 1968 wits: 24" W. Pine SI3E 15.5", LAND 5" Spruce S44# 21.7' "1/45 NBT" SURVEYOR 16" H. Pine \$43M 47.2". Bearings are Bearings are magnetic magnetic. CAND

33981 Surveyor's Michigan License No.

for the Michigan Department of Natural Resources - Forest Management Division