LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

	Filing	g Requirement of Act 74, I	Mich. P.A. 197	U					
For corners in			1						
Iran	Located In:	Corner Code #							
(County) 1. Public Land Survey									
	T <u>44H</u> R T <u>44H</u> R TR								
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR_ S TR_			Regi	ster of Dec	ds Stan	np&Fi	le Nu	mber
4. Lot No, Reco	rded Plat		_	1 A B	C D E	F G	 	<mark>∳</mark> "i	<u>. t</u>
		Jul 08 1997		2 - 6-	╅	- ! -	- - -	- <u>2</u> -	— <u>i</u> –
L Stephan J. Szyszkoski	II	Jul 01 1997		3	 	 	 	<u>†</u>	
requirements of P.A. 74, Michiga	en P.A. of 1970, the come	, 19 do hereby: r points mentioned in lines 1 and :	à above were in	:[7			i_l		—12-
conformance with regulations and	d rules therefore as required	d in the current menual of survey in: snagement or by a decree of a Cour	structions of the	5			15		
that the corner points mentioned	In lines 3, 4 and 5 above v	vers in conformance with the rules	of the Michigan	7 18-	TiT.	Ï		\Box	
Board of Land Surveyors or by recovered, found as expressed by		Law; established, re-established	, monumented,	8 -19-	20	_21	22	-23	 24-
		and man a march monoral		9		$\bot \bot$	\bot	44	1
NOTE: Not more than 2 con on this certificate.		i esta rearge, may be recorded		10-30-	! 	_2B	27	-26	_ —2:5-
				11	+++		++-	\dashv	+
				12 31-	3/2	33		-3 ¹ 5	3 ₆ -
				_ل_ادر				ليـــــــــــــــــــــــــــــــــــــ	
(11) Corner common to Section the original record to Section the original record stated or Mitnesses to corner: Mite Sp. (J1) Quarter corner common to Pine stump corresponding to coto corner: Forked 81. Spruce	ns 2-3 T44M-R31M and 3 of 40.00 ch. west of n his certificate date pruce 5 S27M 65.5 link n Section 2 T44M-R31M a description of the ori	the 1/4 corner between Secti d March 19, 1969. Corner mo s, White Spruce 5 N881/2M 60 and Section 35 T45M-R31N. C ginal corner monument. Set	tablished in 196 ons 2 and 35, ra nument: 1° I.D. .5 links, Trembl orner remonument 1° I.D. x 36° ir	ither thi x 36° ii ing Aspe ed in 19 on pipe	on proport on pipe w on 6 N43E 168 by A.O with 4° a	ionate t ith 4° a 27.5 lin . Enger,	o the c luminum ks. RLS in	origin e cap. n a 22	ai ' w.
•		thod applied in restoring or ree	-						
(II) Recovered the 1968 monum M. Spruce MBT's, neither one marked 4 new accessories as c and 8.Wheeler, Baraga Distric (J1) Recovered the 1968 monum condition, and at record bear visible. Left the monument i and 8.Wheeler, 8araga Distric	showing signs of the described below. This of Office, MDNR. sent, as described, wiring and distance from in place and marked for	markings. No evidence exist corner is being recorded to th a 4° dia. cast aluminum % Enger's witnesses, now both	s of the Aspen M update the acce ichigan Dept. of rotting stumps	BT. Lei ssories. Matural with mea	t the mon Corner Resource Isuring no	ument in rewitnes s tablet tch and	place sed by , in go scribin	and D.Lam and ng	pela
, C. Description of monument	for corner and accesso	ries established to perpetuate	ocating the positi	on of the	comer				

(II) Found 1° pipe with 4° MONR cap. (J1) Found 1 pipe with 4 MDNR cap. Blazed and scribed the following: Slazed and scribed the following: 16" Spruce SOZE 30.8" 1/45 MBT" 16" Spruce S65W 71.5" 1/45 MBT" 5" N. Spruce N86E 31.7" "\$35 NBT" STEPHAN J. 8" N. Spruce S17E 86.7" "S2 NBT" "1/45 HBT" "1/45 HBT" SZYSZKOSKI 5" R. Pine S49W 46.3" S3 MBT 3" Red Pine NO7W 45.1" 2" N. Spruce N16N 26.4" S34 NBT 4" Spruce N79E 29.3" LAND SURVEYOR Squared a cut-off cherry 1.4' west of Bearings are magnetic. the corner. Bearings are magnetic.

33986

Surveyor's Michigan License No.

For the Michigan Department of Matural Resources - Forest Management Division