LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For comers in				ı			
Iran	Located In:	Corner Code i	,				
(County)							
1, Public Land Survey	T_44H R_	31W K10		İ			
	, Ţ Ŗ			-			
	<u>├</u>						
2. Property Controlling	S_24_T_44HR_	31N 14	<u> </u>				
in Section 3. Miscellaneous	S TR_						
Property in Sec.	S			_	Decleter of F	lande Stam	p & File Number
				<u>*</u>	redister of r	Adda Gram	p a r no rromoer
4. Lot No , Reco	orded Plat					_,	
5. Private Claims				ı Å	BCD	E F G 1	HIJKLI
		Jul 08 1997		2 -	- ∮	┼╌┋╌┼╌	à─┼─┆─┼─┆ ─
Steeben 7 Stunthooki		Aug 27 1997		3 -		+++	
requirements of P.A. 74, Michk	_, in a field survey on _	noints mentioned in l	_do hereby state that u inea 1 and 2 above we		-7	- ; -;	10
conformance with regulations an	nd rules therefore as required	in the current manual	of survey instructions of	of the	 		
United States Department of the that the corner points mentions	d in lines 3, 4 and 5 above w	ere in conformence w	ith the rules of the Mich	Nigen _	-1817-	-10-1-1	, 5 1 -
Board of Land Surveyors or a recovered, found as expressed to		Law; established, re	established, monume	inted, 6	19 20		22 23 24
•				ے و			
NOTE: Not more than 2 co	mens, all in the same town	and range, may be	recorded	10-	_3029_	1 28 2	2726- 25
		•		11	+	1-1-	┊
				12	_3132	-333	36-35-36-
				13	_1. 11_		
survey by John R. Garske, P. M/3" sq brass cap". (14-Sec. 24) South 1/16 cor- on line between Section cor- aluminum cap. Mitnesses to B. Description of corner ex- (K10) Found a MMPCO concret- which is stamped "Misconsin- the monument as a reference monument. The computed cor- Left the reference monument	ner between Section 24, ner 19.972 ch. South an corner: Basswood 13 M6 Midence found and/or med e monument, a 7° trunca Michigan Power Company to the original corner ner position was not us	T44M-R31M and Sec d 1/4 Corner 19.97 OE 50 links, Sugar thod applied in restorted ted right rectangu 44-31 1/4 25-26 3 and reestablished to establish of	etion 19 T44M-R30M. 12 ch. Horth. Corn Haple 13 S72M 33. Dring or reestablishin plar concrete pyram 139' S. to cor". T the corner due so reestablish any o	Corner es mer monument 5 links". ing corner: nid with a 3 the MMPCO wi buth (astron other corner	tablished i : 1° I.D. x Found no su * square br tnesses wer omic or tru s during th	n 1969 by A 36" iron p bsequent rec ass tablet : e not recove e south) 33 e course of	.0. Enger, RLS ipe with 4" cord. affixed on top ered. Accepted 9.00' from the this survey.
Baraga District Office, MDH (14-Sec. 24) Recovered the good condition, and at reco the monument in place and m District Office, MDHR.	R. From the monument, 1969 monument, as descr rd bearing and distance arked two new accessori	the water's edge i ibed, with a 4° di from the 1969 wit es as described be	s south 71 ft. The a. cast aluminum Minesses, both found Plan. Corner rewit	e north edg Hichigan Dep Hin good co Enessed by D	e of a catt t. of Matur ndition wit .Lampela an	ail marsh 1: al Resource: h overgrown	s south 50 feet. s tablet, in blazes. Left
C Description of monumen (K10) Found WAPCO concrete	t for corner and accessor	des established to p Found 1 page wi	perpetuate locating the	he position o	f the come	Jacks.	
monument 339' N. of corner.	Blazed and Bla	zed and scribed th	me following:	A	OF A	ICHICA .	
scribed the following beari: 6" W. Pine S46E 18.0'		Sugar S14E 9.6' Sugar N48N 30.6'	"1/16S BT" "1/16S BT"		STEPHA	N J.	Ł
_		1969 witnesses:		# £/	SZYSZKO	oski 🔭	·
	- ·	Basswood N63E 32.	9.	17.	LANI SIIRVEY		¥ E
8° Spruce \$69M 15.2' Ri Placed a squared spruce pos		Sugar S75W 22.1' rings are magnetic		# 5 /	No.	158	#
Bearings are magnetic.		. Congr. die megnerer		1	3398	6	·
1		_		*	AND	4 1	
The state of the s	1 de a	1.1.	5 .4.	$\mathcal{L}_{\mathcal{L}}$	f R	1997	
Signed by \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	- y conjus	TAL.	Date _	def	<u>". o, </u>	////	
Surveyor's Michigan License	1 (NO. V						