SURVEY & REMONUMENTATION

JAN 1 3 1998

IRON COUNTY MICHIGAN RECEIVED FOR RECORD

-	 -	A. /

97 DEC 23 PM 1: 26

Iron Located In: Corner Code #		ORNER RECORDATION Requirement of Act 74, M	CERTIFICATE ich. P.A. 1970	e Regards e Ciliad of	Silie Silie	
1. Public Land Survey T. 4AN R.32W T. R.		ŀ		,	The state of the s	
T. R.		Corner Code	#:	• .		
2. Property Controlling S_T_R 3. Miscellaneous S_T_R 3. Miscellaneous S_T_R 4. Lot No	TR TR					
Ouarter Corner Sec. 6 and 7, T44N, R32W I, _Gary L, Pisoni, in a field survey on _November 3 19 97 do hereby state. that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and /or that the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original Corner: Cherry Post Original Boaring Trees; Fir 10" \$20° E 22 links[14.52] feet) Fir 8" N40° W 15 links[9.90 feet) On 11-1-71, Arthur O. Enger, RLS with the Michigan Dept. Of Natural Resources, restored the corner position proportionately and on line between the Section Corner 39,387 chains to the East and the Section Corner 38,759 chains to the West. Set a:4 inch diameter aluminum capped pipe monument, 3 feet long, 12 linches above ground. Recorded in Land Corner Certificate L. 1, Pages 191-192, on June 27th, 1973. 1971 Bearing Trees; Red Oak 16" N20° E 20.0 feet Sugar Maple 5" \$31° W 8.9 feet B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Red Oak 18" N23° E 20.3 feet Sugar Maple 5" \$31° W 8.9 feet Corner record research on file with County Representative.	ontrolling S T R S T R S T R R S T R R R R R R R R			Register of Deeds	s Stamp & File Nun	nber
Ouarter Corner Sec. 6 and 7, T44N, R32W I, _Gary L, Pisoni, in a field survey on _November 3 19 97 do hereby state. that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law and /or that the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original Corner: Cherry Post Original Boaring Trees; Fir 10" \$20° E 22 links[14.52] feet) Fir 8" N40° W 15 links[9.90 feet) On 11-1-71, Arthur O. Enger, RLS with the Michigan Dept. Of Natural Resources, restored the corner position proportionately and on line between the Section Corner 39,387 chains to the East and the Section Corner 38,759 chains to the West. Set a:4 inch diameter aluminum capped pipe monument, 3 feet long, 12 linches above ground. Recorded in Land Corner Certificate L. 1, Pages 191-192, on June 27th, 1973. 1971 Bearing Trees; Red Oak 16" N20° E 20.0 feet Sugar Maple 5" \$31° W 8.9 feet B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Red Oak 18" N23° E 20.3 feet Sugar Maple 5" \$31° W 8.9 feet Corner record research on file with County Representative.	, Recorded Plat		A	BCDEF	G н I J К	ъ_м
t, Garv L. Pisoni , in a field survey on November 3. 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original corner established in July of 1849 by Zelotes B. Searls, US.Deputy Surveyor. Original Boaring Trees; Fir 10" S20°E 22 links114.52 feet) Fir 8" N40°W 15 links 19.90 feet) On 11-1-71, Arthur O. Enger, RLS with the Michigan Dept. Of Natural Resources, restored the corner position proportionately and on line between the Section Corner 33.937 chains to the East and the Section Corner 38.759 chains to the West. Set a 4 inch diameter aluminum capped pipe monument, 3 feet long, 12 inches above ground. Recorded in Land Corner Certificate L. 1, Pages 191-192, on June 27th, 1973. 1971 Bearing Trees; Red Oak 16" N20°E 20.0 feet Suger Maple 5" S31°W 8.9 feet B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original B.T.s found. On 11-3-97 found the monument as set by Arthur O. Enger, and the following bearing trees; Red Oak 18" N23°E 20.31 feet Sugar Maple(DBL) 8" S32°W 9.00 feet Corner record research on file with County Representative.	ims	<u> </u>	1	6 5 5	3-12-1	
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original corner established in July of 1849 by Zelotes B. Searls, US.Deputy Surveyor. Original Corner: Cherry Post Original Boaring Trees; Fir 10" \$20° E 22 links(14.52 feet) Fir 8" N40° W 15 links(9.90 feet) On 11-1-71, Arthur O. Enger, RLS with the Michigan Dept. Of Natural Resources, restored the corner position proportionately and on line between the Section Corner 39.987 chains to the East and the Section Corner 38.759 chains to the West. Set a 4 inch diameter aluminum capped pipe monument, 3 feet long, 12 linches above ground. Recorded in Land Corner Certificate L. 1, Pages 191-192, on June 27th, 1973. 1971 Bearing Trees; Red Oak 16" N20° E 20.0 feet Sugar Maple 5" S31° W 8.9 feet B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original B.T.s found. On 11-3-97 found the monument as set by Arthur O. Enger, and the following bearing trees; Red Oak 18" N23° E 20.31 feet Sugar Maple 5" S31° W 9.00 feet Corner record research on file with County Representative.	Sec. 6 and 7, T44N, R32W		3	• -		-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: Original corner established in July of 1849 by Zelotes B. Searls, US.Deputy Surveyor. Original Corner: Cherry Post Original Corner: Cherry Post Original Bearing Trees; Fir 10" \$20° E 22 links(14.52 feet) Fir 8" N40° W 15 links(9.90 feet) On 11-1-71, Arthur O. Enger, RLS with the Michigan Dept. Of Natural Resources, restored the corner position proportionately and on line between the Section Corner 39.987 chains to the East and the Section Corner 38.759 chains to the West. Set a 4 inch diameter aluminum capped pipe monument, 3 feet long, 12 inches above ground. Recorded in Land Corner Certificate L. 1, Pages 191-192, on June 27th, 1973. 1971 Bearing Trees; Red Oak 16" N20° E 20.0 feet Sugar Maple 5" \$31° W 8.9 feet B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original B.T.s found. On 11-3-97 found the monument as set by Arthur O. Enger, and the following bearing trees; Red Oak 18" N23° E 20.3 feet Sugar Maple(DBL) 8" \$32° W 9.00 feet Corner record research on file with County Representative.	uirements of P.A. 74, Michigan P.A. 2 above were in conformance wit current manual of survey instruction reau of Land Management or by a dementioned in lines 3, 4 and 5 above 3 abord of Land Surveyors or by a De	of 1970, the comer points ith regulations and rules the solution of the United States Departed of a Court of Law and were in conformance with ecree of a Court of Law; e	mentioned 5 perefore as 6 partment of 7 for that the 7 the rules of 8 stablished, 9		1 22 23	-12
A. Description of original monument and accessories and/or subsequent restoration: Original corner established in July of 1849 by Zelotes B. Searls, US.Deputy Surveyor. Original Corner: Cherry Post Original Bearing Trees; Fir 10" S20° E 22 links(14.52 feet) Fir 8" N40° W 15 links(9.90 feet) On 11-1-71, Arthur O. Enger, RLS with the Michigan Dept. Of Natural Resources, restored the corner position proportionately and on line between the Section Corner 39.987 chains to the East and the Section Corner 38.759 chains to the West. Set a 4 inch diameter aluminum capped pipe monument, 3 feet long, 12 inches above ground. Recorded in Land Corner Certificate L. 1, Pages 191-192, on June 27th, 1973. 1971 Bearing Trees; Red Oak 16" N20° E 20.0 feet Sugar Maple 5" S31° W 8.9 feet B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original B.T.s found. On 11-3-97 found the monument as set by Arthur O. Enger, and the following bearing trees; Red Oak 18" N23° E 20.31 feet Sugar Maple(DBL) 8" S32° W 9.00 feet Corner record research on file with County Representative.	ore than 2 corners, all in the same town a		11	30 - 29 - 2		
Fir 10" S20° E 22 links(14.52 feet) Fir 8" N40° W 15 links(9.90 feet) On 11-1-71, Arthur O. Enger, RLS with the Michigan Dept. Of Natural Resources, restored the corner position proportionately and on line between the Section Corner 39.987 chains to the East and the Section Corner 38.759 chains to the West. Set a 4 inch diameter aluminum capped pipe monument, 3 feet long, 12 inches above ground. Recorded in Land Corner Certificate L. 1, Pages 191-192, on June 27th, 1973. 1971 Bearing Trees; Red Oak 16" N20° E 20.0 feet Sugar Maple 5" S31° W 8.9 feet B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original B.T.s found. On 11-3-97 found the monument as set by Arthur O. Enger, and the following bearing trees; Red Oak 18" N23° E 20.31 feet Sugar Maple(DBL) 8" S32° W 9.00 feet Corner record research on file with County Representative.	orner established in July of 1849 by 2 orner: Cherry Post		1			-
restored the corner position proportionately and on line between the Section Corner 39.987 chains to the East and the Section Corner 38.759 chains to the West. Set a 4 inch diameter aluminum capped pipe monument, 3 feet long, 12 inches above ground. Recorded in Land Corner Certificate L. 1, Pages 191-192, on June 27th, 1973. 1971 Bearing Trees; Red Oak 16" N20° E 20.0 feet Sugar Maple 5" S31° W 8.9 feet B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: No evidence of original B.T.s found. On 11-3-97 found the monument as set by Arthur O. Enger, and the following bearing trees; Red Oak 18" N23° E 20.31 feet Sugar Maple(DBL) 8" S32° W 9.00 feet Corner record research on file with County Representative.	Fir 10"					
Red Oak 18" N23° E 20.31 feet Sugar Maple(DBL) 8" S32° W 9.00 feet Corner record research on file with County Representative.	the corner position proportionately an hains to the East and the Section Co aluminum capped pipe monument, 3 ner Certificate L. 1, Pages 191-192,	nd on line between the Sect forner 38.759 chains to the 3 feet long, 12 inches above	tion Corner West. Set a 4 inch ground. Recorded	in .		-
Red Oak 18" N23° E 20.31 feet Sugar Maple(DBL) 8" S32° W 9.00 feet Corner record research on file with County Representative.	Red Oak	· -		1 71	CALL OF WICH	
Red Oak 18" N23° E 20.31 feet Sugar Maple(DBL) 8" S32° W 9.00 feet Corner record research on file with County Representative.	on of corner evidence found and/or m	nethod applied in restoring	or reestablishing co	orner:	GARY E	A TANA
Red Oak 18" N23° E 20.31 feet Sugar Maple(DBL) 8" S32° W 9.00 feet Corner record research on file with County Representative.	ce of original B.T.s found. 97 found the monument as set by Art	rthur O. Enger, and the folio	owing bearing trees	* * * * * * * * * * * * * * * * * * *	PISONI LAND SURVEYOR	*
			1 1 21			0,1
5 to the corner and accessoring established to pernetuate locating the position of the corner:	cord research on file with County Re	epresentative.		***	WAS THE THE	
C. Description of monument for corner and accessories established to perpetuate locating the position of the soliton.	on of monument for corner and acces	essories established to perp	etuate locating the	position of the	corner:	
Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)	nd scribed the following new bearing	trees: (All measurements t	aken to a nail in si			
Sugar Maple 8" S86° E 41,90 feet PEER GROUP APPROV. Sugar Maple 16" N40° W 28,98 feet Steel Sign Post N87° W 0.75 feet Tand. Parkers COUNTE PROPERTY COUNTE PR	Sugar Maple	16" N40° W	28.98 fe	et Saugh	Pason 11-11-	97
97-15 Signed by Nary L. Prom Date November 7, 1997	Hay S. Prom	DateNo	vember 7, 1997			
Surveyor's Michigan License No. 27457 FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, REVISED MAY 14 REVISED JAN. REVISED OCT.	chigan License No. 27457	FORM	APPROVED BY MICHIGAN ST	FATE BOARD OF PROFESSI	REVISED MAY 1 REVISED JAN	14,1975 N., 1983