

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. ~~44-45~~ NR. 32 W.

----- Iron ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sec.'s 1-2-35-36

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 8" Red Pine S 44° W 92 links

"S 2 NBT"

14" Red Pine S 12° E 107 links

"14" N 83° W S 1 NBT"

7" Soft Maple N 82° E 4½ links

"S 36 NBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced corner from one white pine B.T. S 5° W 12 links. B.T. in poor condition. Stump shattered. Scribe marks visible on bearing blaze.

L.E.S. post 32 links north of corner. Found by Forestry Division Survey Crew.

SURVEYORS SEAL

SIGNED

Billy D. Buckler
REGISTERED LAND SURVEYOR

DATE 6/6/57