SURVEY & REMONUMENTATION

JAN 1 3 1998

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD

S	EC	TI	\bigcirc	N

	97 NFC 23 PM 1- 22
SECTION LAND CORN	97 DEC 23 PH 1: 30 L.C. Records L.7 P. 161 JER RECORDATION CERTIFICATE
	irement of Act 74, Mich. P.A. 1970
For corners in	REGISTITE OF DEEDS
iron Located in:	Corner Code #
1. Public Land Survey T 44N R 34W T 43N R 34W T R T R T R	E-13 V E-1
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	1 A B C D P G H I J K L I
Section Corner Sections 32, 33,T44N, R34W Sections 4, 5, T43N, R34W	2 6 5 4 3 2 1 1 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
1, Gary L. Pisoni , in a field survey on No state that under requirements of P.A. 74, Michigan P.A. of 19 in lines 1 and 2 above were in conformance with regrequired in the current manual of survey instructions of the Interior, Bureau of Land Management or by a decree of corner points mentioned in lines 3, 4 and 5 above were	970, the corner points mentioned gulations and rules therefore as the United States Department of a Court of Law and /or that the
the Michigan Board of Land Surveyors or by a Decree re-established, monumented, <u>recovered</u> , found as express	of a Court of Law; established, 10 30 29 28 27 26 25 sed below:
NOTE: Not more than 2 corners, all in the same town and ran on this certificate.	nge, may be recorded
 A. Description of original monument and accessories an Original corner established in 1846 by William A. Burt Original Corner: Maple Post Original Bearing Trees; 	nd/or subsequent restoration: t, U.S. Deputy Surveyor.
Yellow Birch 18" Sugar 10" On 7/29/77, Arthur O. Enger RLS, DNR, found an old corner position. Position checks with other corners i cap stamped as follows: DNR, T44-43N, R34W, S32 L. 1, Page 542 on 9/12/77.	N 19° E 42 lks (27.72 feet) N 08° W 22 lks (14.52 feet) d scribed white painted cedar post marking in the area. Set a 1" x 36" iron pipe with a 3 3/4" dia. aluminum 2, S33, S5, S4, RLS 1358l. Recorded in Land Corner Certificate
1977 Bearing Trees Sugar Maple 5" Sugar Maple 4"	N 41° W 14.2 feet PEER GROUP APPROVED S 87° W 5.1 feet Jun 8. From 12-19-97
B. Description of corner evidence found and/or method	applied in restoring or reestablishing corner:
No evidence of original B.T.s found	
On November 28, 1997, found monument as set by Sugar Maple 5" Sugar Maple 6"	Arthur O. Enger RLS in 1977 along with the following bearing trees: N 53° W 14.32 feet S 76° W 5.13 feet
I accept the DNR monument as the best available ev	vidence for restoring the corner position.
Corner record research on file with County Represen	ntative.
C. Description of monument for corner and accessories Blazed and scribed the following new bearing tree. Utility Pole No. # on pol Baisam 8" Steel sign post 6'	
97-8a Signed by Lay L. From	Date December 16, 1997 PISONI Date December 16, 1997 SURVEYOR
Surveyor's Michigan License No. 27457	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SHAVENORS, JAN. 28-19-1 REVISED AND 1983 LA WINSED OCT. 1995