## STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

## LAND CORNER RECORD

		Iron-Marquette COUNTY	
		T 45N R 30-31W	
DESCRIPTION OF CORNER	N 1/16 corner between Sections	s 7 and 12	
CORNER MONUMENT	1" I.D. x 36" iron pipe with A	aluminum cap	
	W. Spruce 5 N36°E 1132	lks. "1/16 S BT"	
N	W. Spruce 10 S48°W 742		
12	AND		
CIRCLE CORNER REGISTE	RED		

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Monument placed by proportionate measurement on line between Section Corner 60.052 chains south and Township Corner 101.941 chains north. Found no evidence that a corner had ever been established here previously.

This corner falls in a depression east of a NE'ly trending ridge similar to one the top of which is recorded in the original field notes as being 60.00 chains north of the SE corner of Sec. 12. If the corner were placed about 60 links west of the position selected here, it would fall very near the top of this ridge. This raises a doubt as to whether the monument found at the SE corner of Sec. 12 is in fact the original corner. As proof to the contrary is difficult, the SE corner of Sec. 12 was left to stand as found.

Variation at this corner is about 2015' West.

SURVEYOR'S SEAL

SIGN

REGISTERED LAND SURVEYO

ATE 10/20/69

DISTRIBUTION:

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing