LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

	(IRON COUN			
FOR CORNERS OF -:	LOCATED IN	I - :	CORNER CODE NUMBER South Meander Corner	
1. PUBLIC LAND SURVEY	T. 45 N.	R. 31 K.	Between K-7 & K-9	
2. PROPERTY CONTROLL- 23 ING IN SECTION				
3. MISCELLANEOUS PROPERTY IN SECTION	,T N.	RE.		
4. LOT NO, RECO	RDED PLAT_			
5. PRIVATE CLAIMS				REGISTER OF DEEDS STAMP AND FILING NUMBER
Keith L. Sackett				
Section Corner : 1/4 corner falls	: Restored 31.150 chai s in lake. ned on line	l on south ins south	ed in restoring or re-establishing shore of Hickman Lake and Section Corner 47. Section Corner 20.000	on line between 2745 chains north.
3" Tamarack N8: 3" Tamarack S	: Set 1" 15°W 28.9 16 3°E 14.3 16 .D. x 32" 16 14.4 ft.,	i.D. x 32" it., MC, Ni it., MC, Ni iron pipe	iron pipe with 4" alu BT BT with 4" aluminum cap. T	
SIGNED BY			DATE	······
SURVEYOR'S MICHIGAN REGI	STRATION N	O		(SEAL)
FOR STATE AND UNITED STA	ATES AGENC	ES:		THE OF MICHAEL
SIGNED BY	CHIPTON MINY	PAREN	DATE 9	S. III SE
APPROVED AND SIGNED BY	MICHIGA	REGIOTERED LAN	· · · · · · · · · · · · · · · · · · ·	(SEAL)
Mich			atural Resources	The state of the s
SURVEYOR'S MICHICAN REGI	STRATION N	O. 19006		MAN DE LAND SUFFERENCE