## LAND CORNER RECORDATION CERTIFICATE Elling Requirement of Act 74, Mich. P.A. 1970

For	corners in		rang nequirement of Act 14, Mich.		
	+Caunty)	_	Located In:	Corner Code ##	
1.	Public Land Survey		T 45N R 33N	M13	
			T 45N R 33W	613	
			T R		
			T R		
2	Property Controlling	S	T R		

Register of Deeds Stamp & File Number

4	Lot No.	

5. Private Claims

in Section 3. Miscellaneous

Property in Sec.

G13 February 25, 1995

I, Stephan J. Szyszkoski , in a field survey on HI3 October 09, 1995 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

(HI3) Quarter corner common to Section 34 T45N-R33N and Section 3 T44N-R33N. Corner established in 1845 by Austin Burt as follows: "Mest on South side of Sec. 34...36.00 A ledge of Greenstone Rock 20 ft. high facing the Worth C. £&W. 40.00 Set Maple Post Gr. Sec. Cor. Cedar 12 N33E 5, Y. Birch 10 N36N 24;...59.00 Enter Swamp C. MSM...76.00 Leave Swamp C MNM.

(GI3) Corner common to Sections 33-34 T45M-R33M and Sections 3-4 T44M-R33M. Corner restored in 1984 by Keith Sackett, RES who placed a 1° I.O.x32° iron pipe with 4° aluminum MONR cap. No witnesses noted on the 1984 LCRC.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(HI3) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner on the ground. Reestablished the corner on a straight line between adjacent section corners 2637.11 feet east and west. At this position the swamp and ledge calls noted above check well with the record. The two stream calls which fall in between the swamp edges at 59.00 and 76.00 chains are now obliterated as they fall in a large beaver flooding. At the position for the corner, I placed a 1° I.O.x32° iron pipe capped with a yellow plastic cap stamped "MICH DNR LS 33986".

(G13) Found and accepted a 1° I.D. iron pipe with 4° aluminum MDMR tablet, appropriately stamped. Distance east to "Compact Greenstone" noted in the original record checks but the call is not very distinct. Distances east and west to recorded corners check well with the record. Left the monument in place and marked four witnesses as described below.

## C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (H13) Set 1" pipe with plastic cap.

(G13) Found L" pipe with MDNR cap Blazed and scribed the following bearing Blazed and scribed the following new LIBES! bearing trees: 12" Spruce N76E 24.8" "1/45 NBT" 5" Spruce 520# 29.8" "S4 NR!" 5" Balsan 543E 9.9' "1/45 NBT" 6" Spruce N89N 12.4" "S33 NBT" 12" Maple \$15W 38.6" "1/45 HBT" 6" Balsam \$06W 27.2" "S4 NBT 9° Balsam MS3M 34.9' "1/45 NBT" 10" Aspen N76E 28.8" "S34 NBI" Face of large rock N45E 3.5° Bearings are magnetic. Placed a 4 Cedar post adjacent Bearings are magnetic.

SZYSZKOSKI LAND SLIRVEYOR

33986

10-19-93

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 26, 1971 For the Michigan Department of Natural Resources - Forest Management Givision BEVISED JAN . 1983