## LAND CORNER RECORDATION CERTIFICATE Filing Regulzement of Act 74, Mich. P.A. 1970

Fo	or corners in Iron (County)	, , , , , , , , , , , , , , , , , , ,	
_		Located In:	Corner Code ≠≠
1.	Public Land Survey	T <u>45N</u> R 3 <u>3N</u> T <u>45N</u> R 3 <u>3N</u>	J13 K13
		T R	
2	Property Controlling in Section	S T 45K R 33N S T R	16

Register of Deeds Stamp & File Number

4. Lot No.	. Recorded Plat

		. , ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
5.	Private Claims	

3. Miscellaneous

Property in Sec.

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

## A. Description of original monument and accessories and/or subsequent restoration:

(JI3) Quarter corner common to Section 35 I45N-R33N and Section 2 I44N-R33M. Corner reestablished by proportionate measurement in 1964 by Neal Sperhake, RLS: Galvanized iron pipe, 3 ft. long, 1 dia, with aluminum cap. Spruce 8 S73E 30 links, Cherry 9 N23E 62 links. Sperhake notes distance east and west to adjacent section corners to be 39.935 chains.

(K13) Corner common to Sections 35-36 F45N-R33M, and Sections 1-2 T44N-R33M. Corner remonumented in 1957 by Billy O. Buckler RLS from the remains of an original bearing tree: Monument is 1° pipe with 4° brass cap witnessed by 8° Red Pine S44M 92 links, 14° R. Pine S12E 107 links, 7° Soft Maple N82E 4.5 links.

(16-Sec. 35) East 1/16 corner between Section 35 T45N-R33N and Section 2 T44N-R33N. Corner not established in the original survey. Established by Neal Sperhake for Kimberly-Clark Corp. ca. 1964.

## B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(J13) Found the 1964 monument in good condition, at record bearing and distance from the Spruce MBT, now 20° dia. With healed blazes. The Cherry was not recovered. Left the monument in place and marked three new bearing trees as described below. Found the distance east to Section corner to be 39.8945 chains.

(X13) Found and accepted the 1957 monument in good condition and at substantially record bearing and distance from the 3 1957 witnesses: The 14° Red Pine was observed to be SOSE. Both pines are in good condition with healed blazes. The Soft Maple is dead and down - only a stump remaining. Left the monument in place and marked 2 new bearing trees as described below.

(16-Sec. 35) Found a Kimberly-Clark Monument: A 1° I.D. iron pipe capped with a 4° aluminum cap, stamped with appropriate markings and "Sperhake RLS 7876". I found the monument to be 0.75' South of a straight line between adjacent corners, and 0.44' East of the midpoint. I accepted the monument as a careful and faithful determination of the position of the corner. Left the monument in place and marked witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(J13) Found 1" pipe with 4" aluminum Kimberly Clark cap. Blazed and scribed the following new bearing trees: 2" Spruce N23M 30.7' "1/4S MBT" 6" Balsam S76M 27.4" "1/4S MBT" 13" Balsam S27M 22.4" "1/4S MBT" (RI3) Found 1" iron pipe with 4" brass MI Dept. of Conservation cap. Blazed and scribed the following:

14" Cedar M60E 64.3" "\$36 MBT" 12" R. Pine M52M 49.5"(slope) "\$35 MBT"

Bearings are magnetic

(16) Found a 1° iron pipe with a 4°
Kimberly-Clark cap. Blazed and scribed
the following bearing trees:
5° Balsam M48E 20.0° "1/16S BT"
6° Balsam M17N 29.7° "1/16S BT"
6° Spruce \$60N 13.8° "1/16S BT"
7° Haple \$16N 21.7° "1/16S BT"
8earings are magnetic.

Bearings are magnetic.

STEPHAN J.
SZYSZKOSKI
LAND
STIRVEYOR
No.
Doctor
33986

3-1-95

For the Michigan Department of Management Division.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM 28, 1971

† Management Division.

REVISEO MAY 14, 1975

REVISEO JAM. 1883

Surveyor's Michigan License No.

The 1964 MBT: Spruce 20" S65E 19.0"