LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

lron (County)	_ Located In:	Corner Code #				
1. Public Land Survey	T 46N R 33W T 46N R 33W T R	J1 				
2. Property Controlling in Section	S T R S T R					
3. Miscellaneous Property in Sec.	S T R R		Register	of Deeds Stam	np & File Nur	nber
4. Lot No. , Red 5. Private Claims	corded Plat	 	1 A B C	DEFG	H	K L N
		12/2009	3			
ı, Stephan J. Szyszkoski , in		12/2009 do hereby state	4	_ _ _ _	1O1	112-
•	74, Michigan P.A. of 1970, the corner regulations and rules therefore as require	•	- 1 1 1	444		
	Department of the Interior, Bureau of Li			-1716	—15——1	413
a Court of Law and /or that the o	orner points mentioned in lines 3, 4 and	5 above were in conformance wit	h 7	+	 	
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,			¹ , 8 — 19——	-20	_222	3——24—
re-established, monumented, recove	ered, found as expressed below:		9			
NOTE: Not more than 2 corners, all in the same town and range, may be recorded				-2928	—27——2 	625
on this certificate.	ers, an in the same town and range	, may be recorded	11			
			12 31	35 33		36-

- A. Description of original monument and accessories and/or subsequent restoration:
- (J1) Quarter corner common to Section 35 T47N-R33W and Section 2 T46N-R33W. 1846 Established by Austin Burt Deputy Surveyor. Set Spruce post. Spruce 7" N33E 10 links, Tamarack 6" N40W 28 links. Found no subsequent record.
- (I1) Corner common to Sections 34-35 T47N-R33W and 2-3 T46N-R33W. 1846 Established by Austin Burt Deputy Surveyor. Set Fir post. Y.Birch 8" N57E 60 links, Y.Birch 10" N43W 32 links. 1852 Francis Houck Deputy Surveyor marked Fir 10" S20W 26 links, Fir -- S51E 49 links. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (J1) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner on the curved Township line and by single proportionate measurement to the original record between Section corner 2635.59' east and Township corner 23603.70' west.
- (I1) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner on the curved Township line and by single proportionate measurement to the original record between Section corner 5271.19' east and Township corner 20968.11' west.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (J1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. The mon. leans a little to the east due to rock. The center of the cap marks the corner position. Set measuring nail with MDNR tag in the side of: 5" Maple N45E 14.0' mrkd "1/4S NBT" 8" Spruce S29E 12.2' do 4" Maple S20W 20.0' do 14" W.Pine S78W 18.4' do Set sq'd cedar post near. Bearings magnetic.
- (I1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Balsam NO5E 20.65' mrkd "S35 NBT"

5" Balsam N05E 20.65' 2" Balsam N40E 6.1'

do

5" Balsam N87E 12.15'

do

3" Cherry S71E 6.65'

"S2 NBT"

OF MICA

YSZKOSK LAND

STEPHAN J

SURVEYOR

Set sq'd cedar post near. Bearings magnetic.

Signed by Stephen Synghist.
Surveyor's Michigan License No. 3398

Date

10/06/2009

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROP

gewised they 14, 1975 Minsed Jan., 1983