LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

		!	1
[ron (County)	Located In:	Corner Code #	·
1. Public Land Survey	T 46N R 33W T 46N R 33W	D1 C1	
2. Property Controlling in Section	S T R S T R R		
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No. , Reco	orded Plat		A B S D E F G H I J K L M
above were in conformance with reinstructions of the United States Do a Court of Law and /or that the co	4, Michigan P.A. of 1970, the corner egulations and rules therefore as requestrement of the Interior, Bureau of orner points mentioned in lines 3, 4 are of Land Surveyors or by a Decree	ired in the current manual of survey Land Management or by a decree of nd 5 above were in conformance with	y 5 f 6 18 17 16 15 14 13 15 17
NOTE: Not more than 2 corne on this certificate.	ers, all in the same town and rang	e, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36 13

- A. Description of original monument and accessories and/or subsequent restoration:
- (D1) Quarter corner common to Section 32 T47N-R33W and Section 5 T46N-R33W. 1846 Established by Austin Burt Deputy Surveyor. Set Cedar post. Fir 10" N48E 11 links, Fir 7" N31W 28 links. Found no subsequent record.
- (C1) Corner common to Sections 31-32 T47N-R33W and 5-6 T46N-R33W. 1846 Established by Austin Burt Deputy Surveyor. Set Cedar post. Y.Birch 16" N23E 28 links, Y.Birch 16" N29W 38 links. 1852 -Francis Houck Deputy Surveyor marked Y.Birch 16" S27E 39 links, Y.Birch 16" S32W 57 links. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (D1) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner on the curved Township line and by single proportionate measurement to the original record between Section corner 18449.15' east and Township corner 7790.15' west.
- (C1) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the position for the corner on the curved Township line and by single proportionate measurement to the original record between Section corner 21084.74' east and Township corner 5154.56' west.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (C1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. (D1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in the side of: 6" Sugar N29E 9.1' mrkd "S32 NBT" 4" Tamarack N33W 10.25' mrkd "1/4S NBT" "S5 NBT" do 8" Y.Birch S42E 13.5 2" Balsam S70E 8.2' 6" Sugar S60W 20.6' "S6 NBT" 6" Maple S13W 25.3' do 6" Y.Birch N48W 20.4' "S31 NBT' 3" Tamarack West 8.35' do Set sq'd cedar post near. Bearings magnetic. Set sq'd cedar post near. Bearings magnetic.

Surveyor's Michigan License No.

Date

10/06/2009

For the Michigan Department of Natural Resources, Office of Land and Facilities

16319

FORM APPROVED BY MICHIGAN STATE BOAL

14, 1975 LANDS sed Jan., 1983 Rervised Oct., 1995

STEPHAN J

SURVEYOR

YSZKOSK LAND