LAND CORNER RECORDATION CERTIFICATE

5	Filler	& redonament of ver 14' wie	II. P.A. 197	U					
For corners in			- 1						
Iron	Located In:	Corner Code #							
(County)			ļ						
1. Public Land Survey	T <u>46N</u> R_ T <u>46N</u> R_ TR_								
Property Controlling in Section Miscellaneous Property in Sec.	TR_ S TR_ S TR_ S TR_ S TR_			Regist	er of De	eds St	emp &	File N	lumber
4. Lot No, Reco	orded Plat			1 A B	DE	F G	H	i j	K L
J. F. ING.O CIGIIIO			•	2 6			_[_	Ţ	
•	C7	Jun 25 1998				-i	;	Τí	T
e Stanhan I Cruerbacki	B7	Aug 11 1998	. 45 . 4 4	1 1		Ţ			
, Stephan J. Szyszkoski requirements of P.A. 74, Michic	_, in all werd survey on _ san P.A. of 1970, the come	do hereby state r points mentioned in lines 1 and 2 abo		4 - 7 -	T i T	ا آ آ	—10— 		11°
conformance with regulations an	d rules therefore as required	d in the current manual of survey Instruc	tions of the	5		<u> </u>	_		++
		enagement or by a decree of a Court of I were in conformance with the rules of th		6 -19-	17	-16	15	114-	13
		Law; established, re-established, mo		⋾ ├ ╼╇╼		╅┥	-+-	+	++
recovered, found as expressed b	elow.			0 -19-	2'0	-21	2'2	2'3	
NOTE: Not more than 2 co	mers, all in the same town	and range, may be recorded		9			_		
on this certificate.				10-30-	29-1	_2B	_27_	26	
				11	$\dashv \dashv$	-		\perp	$\bot \bot$
				12 —31—	_32	-33] 3 4	35_	36-
		•		13	<u> </u>	Ĩl	_Ï_	Lī	1.1
B7) Quarter corner common to ost. Spruce 8 S30W 15, Tam C7) Corner common to Section	o Sections 18-19. Esta 10 M70E 2978.50 Set ns 17-18-19-20. Corner t. Position fits good	me and/or subsequent restoration: ablished in 1852 by Zelotes 8. S t post Cor. Secs. 17,18,19,20.* r restored in 1986 by Keith L. S with other corner and land call ?'.*	Found no so ackett RLS	ibsequent 19006: [™] Fo	record. und old	post se	et by (unknowi	n
37) Original post and accer round. Reestablished the co roportionate to the original luminum MDNR tablet, appropri	ssories were not recove orner on a line of mean I record. At the posit riately stamped. Corne	thod applied in restoring or reestab ered. Found no acceptable evide a true bearing between Section o tion for the corner, I placed a er placed and witnessed by D.Law ID iron pipe capped with a 4"	ince of the porners 40.27 1° ID x 32° 1pela and 8.9	esition o 158 ch. ea iron pipe Theeler, B	st_and 3 capped araga Di:	3,7655 with a strict	ch, wi 4° dia Offici	est, be n. cas! e.	eing

Left the monument in place and marked three new accessories as described below. Corner recovered and rewitnessed by D.Lampela and B.Wheeler, Baraga District Office.

 C. Description of moл 	ument for corner	and accessories established to perpetuate locating the pos	ition of the corner
87) Set I' pipe with 4	" MONR cap.	(C7) Found 1" pipe with 4" MDNR cap.	STEPHAN J
lazed and scribed the	following:	Blazed and scribed the following:	1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1
0° Cedar N18E 38.25'	"1/45 NBT"	8" W. Spruce N11E 63.7" "S17 MBT"	S OF STREET
" Auto Cadas Cook an a	بد ف	IT THE H BEACH OTTH IN TO TOTAL HAT?	# #/ SIEPHAN J.

4" Twin W. Birch \$37W 16.7' "\$19 MBT" 9" twin Cedar S02W 29.0" 11" W. Spruce \$73W 62.7" "S19 NBT" (the 9" Cedar leans heavily east) 13" Cedar S61W 64.15" "1/45 NBT" Bearings are magnetic. Distances are to 12" Tamarack MS2W 31.6" do

meas. notch.

Bearings are magnetic. Distances are to meas, notch,

Placed a squared cedar post adjacent.

Signed by Surveyor's Michigan License No.

SZYSZKOSKI

LAND

SURVEYOR