1 AND CODNED DECORDATION CERTIFICATE

	Fili	ng Requirement of Act 74, Mich.	P.A. 1970)							
For corners in			t								
Iron	Located In:	Corner Code #	i								
(County)	_		-								
1. Public Land Survey	T <u>46N</u> R T R T R										
Property Controlling in Section Miscellaneous Property in Sec.	TR S_1 T444 R S TR S T R S T R	34H. 2		Reg	ister	of Dec	eds S	temp	& File	Num	ber
4. Lot No, Recor	ded Plat			A B	<u>- ç</u>	D E	F	G H	1 -	J K	Ļ
	2	Aug 04 1998		≱ 	_	╌┇┷┼		<u>↓</u> .	4-	<u></u> - - - - - - - - - - - - -	_ _ 1.
•	_	Aug 25 1998	:	• 		+		╀╌┼	+	\vdash	4
I, <u>Stephan J. Szyszkoski</u> , in a field survey on				ı	\pm	•	Ы 	-10	<u> </u>	1	-12
conformence with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			vand/or Wachigan	 		17-	-16	15	1		-13 -1
			mented,	1 1	4	20	-21-	22_	2	3	-24-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.			1	1 1	+	29	-28-	-27		6——	-25-
			1 1:	1 31-		32	33-		+	5	- -36

- A. Description of original monument and accessories and/or subsequent restoration;
- (ES) Corner common to Sections 8-9-16-17. Established in 1852 by Zelotes B. Searles: *80.00 Set post Cor. of Secs. 8,9,16,17. Tam 4 \$41 1/2M 89, do 4 M21E 19. August 1954 record by 8.G. Swell for Worhtern Paper Mills at Med Lake Timber and Land Co. state: 1930. M. Cole and R. Sillers found orig. post. No evidence of 8.T.s. Set post. 1954 Peryam and Mickman found Cole's post. No trace of 8Ts or original post. Set pipe at post. Description of corner monument: Pipe and brass cap. Witnesses: Bog, no trees big enough.
- (2-Sec. 21) East 1/16 corner between Sections 16-21. Corner not established in the original survey. Found no subsequent record.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;
- (E5) Recovered the 1954 monument as described, a I ID iron pipe capped with a 2 brass tablet stamped "NORTHERN PAPER MILLS", marked with the incorrect section numbers 8-9-17-18, in good condition. Also found the remains of a post point adjacent and an old squared post I ft. easterly. Found no trace of the original Bis. The post point may possibly be the "orig. post" referred to in the 1954 record. I accept the monument as the best available evidence of the position of the original corner. Left the monument in place and marked new bearing trees as described below. Corner recovered and rewitnessed by B.Wheeler and D.Lampela, Baraga District Office. Two of the MBTs marked had metal location posters attached to them: 3" 8. Spruce with a newer poster, 2" Tam. SW with an old one, (2-Sec. 71) Found no evidence of prior monumentation at the corner position. Established the corner midway and on a line of mean true bearing between Quarter corner 1318.10' West and Section corner 1318.10' East. At the position for the corner I placed a 1' I.D. x 32' iron pipe capped with a 4° dia, cast aluminum MDMR tablet, appropriately stamped. Corner placed and mitnessed by D.tampela and B.Wheeler, Baraga District Office,

C. Description of monument for corner and accessories established to perpetuate locating the position of the (E5) Found 1" pipe with 2" NPH cap. (2) Set 1° pipe with 4° MDNR cap. Blazed and scribed the following: Blazed and scribed the following: STEPHAN J 3" 8. Spruce N83E 21.9" "SQ NRT 24" W. Pine N89W 23.5" "1/165 BT" 2" Tan. S57E 36.8" \$16 N8T 10" Cedar N30E 9.2" SZYSZKOSKI do 2" Tam \$38% 36.5" S17 NBT 10° Cedar S66E 28.8' do LAND 2° B. Spruce N65W 3.15' S8 NBT SURVEYOR 10° Cedar \$29W 65.8' Squared and scribed B. Spruce post Placed a squared cedar post adjacent. adjacent. Bearings are magnetic. Distances are to meas, notch, Bearings Distances are to meas, notch. are magnetic.

33986 Surveyor's Michigan License No.