JACKSON COUNTY APPROVED LAND CORNEI	2		LIBER 140V PAGE /	11
P.A. 345 of 1990		r, Section 26, Henrietta Town	ıship	
Chairman Noon Sult	Ema LAND CORN	NER RECORDATION CERTIFIC	CATE	
Date <u>1/00, ZZ,199</u>	🗗 💮 Filing Requ	rirement of Act 74, Mich. P.A.	1970	
For corners in JACKSON (County)	Located In:	Corner Code #	STATE OF NIC JACKSON CO	
Public Land Survey	Tis Rie	T-11	RECORDE	D
·	T R T R T R	BEMONUMENTA	28 DEC 94 9: Tion	43 A.H.
Property Controlling S	T R	MAY 0 3 1995	GERALD J. Mc REGISTER OF	
Property in Sec. S_	TR	COMMISSIO	Register of Deeds Stamp &	
4. Lot No, Record	ded Plat		A B C D E F G	H 1 J K L
			2 6 5 4	3 2
				10 11 1
I, David E. Erickson, in	a field survey on Octo	of 1970, the corner points mentioned	5	
in lines 1 and 2 above were in co	onformance with regulations	and rules therefore as required in the timent of the Interior, Bureau of Land	6 18 17 16	15 14 1
Management or by a decree of a Cour	t of Law and/or that the corner utes of the Michigan Board of	r points mentioned in lines 3, 4 and 5 f Land Surveyors or by a Decree of a	7 8 19 20 21	22 23 2
Court of Law; established, re-est expressed below:	ablished, monumented, re-	monumented, recovered, found as	9	
NOTE: Not more than 4 corner	s, all in the same town and	d range, may be recorded on	10 30 29 28	27 26 2
this certificate.			12 31 32 33	34 35 3
A. Description of original me	onument and accessorie	es and/or subsequent restoration	13	<u> </u>
1 to Co. a	vey office) indica 988 D.A. Ankrom, I	hear. Field notes dated 9 ate the distance East to " L.S. #21265, recorded the	il-ii as 2004.0 and	NOTCH CO T .
Found 3" x 24" Fi pipe (length unkn fireclay. Pipe 1 faithful perpetua Survey Monument (J	reclay, 1.7' below own) found on north eft in place, too tion of the position CSM) in exact local	hod applied in restoring or reestable we surface of soybean field the side of fireclay. Also long to remove. Accepted ion of the criginal corner ation of found fireclay. The ally on east side of monuments of the side of monuments.	f. A 3/4" (inside did b found pieces of tile d fireclay as a carefu c. Set a standard Jac Top of monument is 1.	l and kson County 7' below
			S 7.00 COARER REMONUS	
Set 4" dia. x 36'	onument for corner and a concrete monumen mped L.S. 29245, 1	accessories established to perpetual to with 1/2" x 36" rebar at 994, I-11	ate locating the position of the	e corner:
S66°W Set spike	e/tag "29 245" in S	outh side of 14" Cottonwood	-	43.11'
S85°W Set spike	/tag "29245" in N	orth side of 11" Cottonwood outh side of 17" Cottonwood	od 5	76.74' 15.90'
N80°E Set spike	in East track of	trail road	4	56.50'
S83°E Set spike	e/tag "29245" in N	orth side of twin 12" and orth side of lone 40" cot	tonwood b	79.97' 76.45'
West County Su	rveyor sign post	52.0 52.0. 5	<u>ن</u> پيس	5
Note: Bearings	are magnetic		ATE	OF MICHIGAN
Note: Bearings	are magnetic			AVID E.
			EF	iiCKSON d Surveyor No.
	n C C . 1			29245

Surveyor's Michigan License No. 29245