BEAG SURVEY &	1
REMONUMENTATION	4

APPROVED LAND CORNER P.A. 3451 of 1999	Witness Corner of Section 31, 1		FEB 0 8 2000		
All all and the second	LAND CORNER RECORDATION	•			
Date 12 2499	Filing Requirement of Act 74,		SECTION		
For corners in JACKSON Located In: (County) 1. Public Land Survey T 1a. Remonumentation 'Other' code T T	18 R 1E 3	dy Reilly - Jackson Co.	2141953 Page: 1 of 1 01/05/2000 09:14A CORREM L-1620 P-1112		
2. Property Controlling in Section S T 3. Miscellaneous S T Property in Sec. S T	RR	Register of Dee	de Stamp & File Number		
Lot No Recorded Plat Private Claims		, A B C	DEFGHIJKLM		
		2 3	5 4 5 2 1		
David E. Erickson, in a field survey or do hereby certify that under requirements of P.A. In lines 1 and 2 above were in conformance current manual of survey instructions of the Uni- ficial manual of survey instructions of the Uni- ficial manual of survey instructions of the Uni-	74, Michigan P.A. of 1970, the corner points with regulations and rules therefore as required States Department of the Interior, Burea for that the corner points mentioned in lines 3	ired in the 6 18 u of Land , 4 and 5 7	15 16 16 14 13		
above were in conformance with the rules of the Court of Law; established, re-established, re-expressed below:		found as	20 21 22 23 24		
NOTE: Not more than 4 corners, all in the on this certificate.	same lown and range, may be recorded	n 1 1	29 28 27 26 25 32 38 34 35 36		
A. Description of original monument	and accessories and/or subsequent r				
The original survey of 1825 notes "In In 1888, H.F. Bean noted "In Lake".	tersect W. Boundary in Lake." No	comer was set and no fajiin	g was noted.		
B. Description of corner evidence four	nd and/or method applied in restoring	or reestablishing comer:			
Corner position falls in Malay Lake. Since no falling was noted for this corner, I believe the only way to establish this position is to intersect the Meridian with the North line of Section 31. Therefore, I re-established the position of this corner by intersecting the Principal Meridian line, between corners "M-10" and "M-11", T1S-R1W, as remonumented, with the North line of Section 31. The North line of Section 31 determined by extending the line between corners "B-11" and "C-11", T1S-R1E, as remonumented, to the Meridian. I then established a Witness Corner (WC) on the Meridian, 633.51 feet North of the calculated position of "A-11", in lake. Set a standard concrete monument on North side of Malay Lake.					
C. Description of monument for corne	r and accessories established to per	petuate locating the position o	f the corner:		
Set a 4" diameter x 38" long concret R1E, 1997, LS #29245".	e monument with Jackson Count	y standard aluminum cap s	tamped *W.C. A-11, T1S-		
N 10° E Set nail & tag #29245, We S 12° W Set nail & tag #29245, Ear N 61° W Southwest corner of hour South South County Surveyor sign por South North edge of Malay Lake West North-South fence East Conter "M-10" T1S-R1W South Corner "M-11" T1S-R1W,	st RR tle fence post se foundation 17 se foundation 13 st 1.6 s 18 so 8 so outh lane 8 se remonumented 14 rner "A-11", T1\$-R1E, in lake 63		DAVID E ERICKSON Land Surveyor No. 29245		
NOTE: Bearings are magnetic			LAND		
Note: This corner is being re-reco		n requirements.			
Signed by Ward Co	Date C	1-21//	<u> </u>		
Surveyor's Michigan License No29	245 FORM APPROVED I	y ngongan state boald of Lang Surveyor Abar	ir, Jan. 24, 1674 Revised May 14, 1878 Revised Jan., 1883 128 For Word Processes Black, 1883		

The state of the s