Surveyor's Michigan License No.

	IACKSON LOUNTY	Tage 1	, 08 , 08			
	ROVED LAND CORNER P.A. 345 of 1990/	A	SECTION 33, RIVES T			
	rman Dem & Luther	NW CORNER,	SECTION 33, RIVES T		707	
	Date Oc7, 30, 1995		ER RECORDATION CERTI		01 PAGE 783	
For (	corners in	Filing Require	ement of Act 74, Mich. P.	A. 1970		
10.	Jackson	Larate Har	0 0.4. //			
	(County)	Located In:	Corner Code ##		E OF NICHIGAN	
• 1	Public Land Survey	7 1s R 1W	E-11	JA	CKSON COUNTY RECORDED	
1. 1	Public Land Survey	T R	44 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4		RECURPED	
		T R		28 DE	C 95 11: <b>86</b> A.H.	
	•	T R				
		TR	ŀ		LD J. McDEVITT	
		T R T R			ISTER OF DEEDS	
_		T R		Register of Deeds	Stamp & File Nui	mber 
	ot No, Record			A B C D	E F G H I J	JKLI
5. r	-nvate Claims		1,0011919191	2 6 5	<del>                                      </del>	ļ _
				3		
<b>7.</b> 1	an T. Cohonnolman	0.	stohom 17 05	4	- <del> </del> - - - -	1
	an L. Scheppelman			5		
	ereby certify that under requireme es 1 and 2 above were in confo			n the 0 18 17	16-15-1-1	'4— <del> </del> —-13—
	nt manual of survey instructions gement or by a decree of a Court					<del>                                     </del>
	e were in conformance with the r			1 13 1 20	21 - 22 - 2	23   24   
	t of Law; established, re-esta	blished, monumented, re-r	monumented, recovered, found	d as 10 30 30		
	essed below: E: Not more than 4 corners	all in the came town a	ad rango may be recorded	11 1	1 2 2 2	25
1401	on this certificate.	s, all ill the same town a	id lange, may be recorded	12 31 32	33 34	 3536
				13		
A. I	Description of original monur HERVEY PARKE		d/or subsequent restoration: OR, SECS. 28, 29, 32			
			200 LINKS; W. OAK 20		S	
	H.F. BEAN		ITNESS FOUND, AND ME	·	—	
	1885	E & W AND FOUND	IT CORRECT BY WITNES:	s		
			E, 440 LINKS; SWP. OF			
	RONALD L. KELLER LCRC - L. 3, P. 237 FOUND FIRECLAY 0.3' BELOW ASPHALT.  RLS #20707 N5°E, P. POLE, 289.97'; N70°E, P. POLE, 175.83';					
	DEC., 1978		187.75'; N/O'E, P. PO!			
	CONTINUED ON BACK		, 200 2, 20	Jan, 194172		
B. (	Description of corner evidence		applied in restoring or reesta	ablishing corner:		
	·					
			3/4" x 24" PIPE ON T			
TIM VAN GIESON'S CAP (24621) IN MONUMENT BOX. EXCAVATED THROUGH MONUMENT BOX AND FOUND BOTTOM 5" OF FIRECLAY DOWN 1.8". ALSO FOUND PIECES OF BRICK						
			FIRECLAY AS A CAREFO			
			NER AS REMONUMENTED		ANDARD	
	JACKSON COUNTY MOD 3/4" PIPE BURIED :		OF FIRECLAY BURIED			
	3/4" PIPE BURIED .	IO THE WEST.	•	\$ 2.00 REMONUM		
				\$ 9.00 CORNER	REMONUMENTATION	
					******	F MO.
					HINE.	///
					S GO ! CONT	ILAN L Eppelman
Ç. E	escription of monument for	corner and accessories e	established to perpetuate loc	cating the position of th	e corner PRO	FESSIONAL
	4				SU SU	RVEYOR No.
	4" x 36" CONCRETE STAMPED "E-11 TIS		KSON COUNTY REMONUME TN MONUMENT BOX.	INTATION CAP		3598 .••
		ER OF FOUNDATION T		3	33.12 PROF	SSIONAL
	n24°w found 60	Od nail in east si	DE OF POWER POLE		33.51	HILLIANS
		CORNER OF HOUSE	— — — —		91.78	
			IN SOUTH SIDE OF PO N NORTH SIDE OF 48"	_	75.96' 88.23'	
		od nail in north s			35.09'	
	SOUTH CENTERLE	ENE OF E-W PAVED R		_	3.0	
	S02°E SURVEY N	MARKER SIGN			28.7'	
	11/2	Lokan !	Date	11/09/95		
Signe	d by Wear / ==	35998	Date	<u> </u>		
A						

E-11, TlS, R1W

A. MAURICE H. MAHIEU CERTIFICATE OF SURVEY RECORDED IN L. 1207, P. 1177 L.S. #28414 DOES NOT INDICATE THE TYPE OF MARKER BUT HAS - AUG. 11, 1989 THE FOLLOWING WITNESSES:

NAIL & TAG IN S. SIDE IF UTILITY POLE N80°E NAIL & TAG IN N. SIDE OF 48" OAK (BEAN) **580°E** NAIL & TAG IN N. SIDE OF 24" OAK S70°E 134.84

RAILROAD SPIKE IN ASPHALT

EAST 1,330.55

RONALD L. ENGER L.L.s. #28409 AUG. 13, 1990 MAY 1, 1991 JULY 22, 1991

CERTIFICATES OF SURVEY RECORDED IN L. 1252, P. 450; L. 1293, P. 1240; L. 1293, P. 1244. ALL HAVE THE

FOLLOWING INFORMATION:

FOUND FIRECLAY POST IN MON. BOX

FOUND IRON AND ILLEGIBLE CAP WEST 0.27 POWER POLE

POWER POLE

N5°E 289.97'
N70°E 175.83' (MAHIEU)
S70°E 187.75' (BEAN & MAHIEU)
S60°E 134.92' (MAHIEU) 48" OAK

10" OAK