JACKSON COUNTY SURVEY & REMONUMENTATION NORTH 1/4 POST, SECTION 16 APPROVED LAND CORNER RIVES TOWNSHIP P.A. 343 of 1929 Chairman <u>Man</u> LAND CORNER RECORDATION CERTIFICATE MAR 1 3 2000 Lico Nov. 10, 1999 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in SECTION JACKSON Located in: Corner Code ## (County) TISRIW 1. Public Land Survey 2139079 Page: 1 of 2 12/06/1999 03:30P **Property Controlling** R L-1618 P-943 in Section __ R . Τ... ___ R Miscellaneous Register of Deeds Stamp & File Number Property in Sec. _ , Recorded Plat ___ Lot No. Private Claims 1, DEAN R. GUTEKUNST , in a field survey on . June 1, 1998 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 10 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration: Original Government Post set by Hervey Parke, Deputy Surveyor, in 1825. Y. Oak 34" N 55 W 66 links (43.56) 39.80 1/2 chains Y. Oak 28" S 27 E 90 links (59.40') Perpetuation by H. F. Bean, in 1885. W. Oak 12" N 47 E 65 1/2 links (43.23') One witness left, Found iron post * B. Walnut 10" S 43 W 56 1/2 links (37,29') Continued on back, B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found capped iron #7863, from above witnesses. Excavated and found FIRECLAY below iron, also found boatspike and a 1/2" X 1 1/2" X 15" bar Corner is approximately I' North of center line of Perrine Road (blacktop) and in line of occupation South. Accepted FIRECLAY as a careful and faithful perpetuation of the position of the original corner as remonumented by Bean in 1885. Set a Standard Jackson County Monument to replace the FIRECLAY and left fireclay and irons buried beside monument. C. Description of monument for corner and accessories established to perpetuate locating the position of the conditions. Corner is a 4" diameter X 30" Cast Iron Harrison monument with a F-5 TISRIW Brass cap stamped LS 18658, which is a standard monument for GUTEKUNST Jackson County. No. 18458 N 65 W 36" Oak 69.18 Pole barn spike and washer on South side. 23" Oak N 45 W 41.56 Pole barn spike and washer on Southwest side. PEL LAND N 55 W 19" Walnut 38.65 Pole barn spike and washer on South side. 7" Walnut S 45 W 43. 57 Pole barn spike and washer on North side. Pole barn spike and washer on North side. S 75 W 9" Walnut 97.33 16" Oak S 60 E 48.38 Pole barn spike and washer on North side.

Steel post and survey marker sign attached

Monument box set by Jackson County Road Commission. Date

South

Surveyor's Michigan License No. ____18658

Signed by .

25.6' *

October 1, 1999

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1943 Continued,



Page: 2 of 2 12/05/1999 03:30P L-1618 P-943

A.) - Perpetuation by Richard E. Gutekunst, RLS#7863, dated March 22, 1968. (stump in 1999)

* S 42 30 W	28" B. Walnut	37.65
** N 64 30 W	30" Oak	69.25'
*** N 46 W	18" Oak	41.58
N 13 30 W	18" Walnut	21.36
S 56 E	12" Walnut	44.91'
S 5 W =	8" Hickory	28.44'
N 6 30 W	12" Walnut	56,59

Found FIRECLAY and boatspike from one witness standing and

stump of other witness.

Not recorded in P.A. - 74.

SURVEY & REMONUMENTATION

MAR 1 3 2000

SECTION