Man. 200 man + 1	* *		
JACKSON COUNTY			
PPROVED LAND CORNER	NE CORNER SECT	ION 14	
P.A. 343 of 1990	L TOMPKING TOWN	ISHIP	#2037791
Chairman Acad Tallan	ner		Liber 1544 Page 360
Date MAY 15,1997	LAND CORNER RECORDATION Filing Requirement of Act 7	TION CERTIFICATE 4, Mich. P.A. 1970	Page 1 of 1 Jackson Co., MI
For corners in	-		Recorded 06/11/97 10:58A
JACKSON Locat	ed in: Corner Code #		Mindy Reilly
(County)		SURVEY &	Register of Deeds
1. Public Land Survey	T18 R 2W	REMONUMENTAT	ON
•••	<u>TR</u>	11211014411111	
	<u></u>	APR 0 7 1998	
	ŢR	AFR 0 1 1330	
2. Property Controlling S	TR		
in Section S 3. Miscellaneous S	TR	SECTION	
Property in Sec. S	T_R	Regi	ster of Deeds Stamp & File Number
1 /opensy in 555.		<u> </u>	•
4. Lot No, Recorded Pla	t	A B	CDEFGHIJKLM
5. Private Claims			1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2 1 2
		3	
			1 1 1 12
IDAVID CLIFFORD in a fi	eld survey on APRIL 10, 1997 do he	reby state that under 4 7-	
	1970, the corner points mentioned in lines 1 refore as required in the current manual of survivors and the current of the curr		- - - - - - - - - - - - - - - - - - -
to the contract Department of the Interior Bi	NASIINTIANS MANACRINEILUIUY A VOCICE VIE	Coditol tall direct	17-16-15-14-13-
Y about of basediness and an arriver of	יסוג ונותר סטונונוטנונטו חוויאוא אאראי אירוויטנונטו אווייסי	ו ו היישטייטייוני או או ופסטו	▗ ▎▕▗╎▗╏╺╏ ╺╂╼┼╍╂╾┼┈╂
Board of Land Surveyors or by a Decre	e of a Court of Law, established, re-establ	819	20 21 22 23 24
recovered, found as expressed below:			
NOTE: Not more than 2 corners, all in	the same town and range, may be record	led j	29 28 27 26 25
on this certificate.		10 - 30	
		11	
		12 31	32 34 35 36
		13	
A Description of original monument	and accessories and/or subsequent rest	toration:	IN FERRILARY 1825 AND
1. POST SET IN ORIGINAL	and accessories and/or subsequent rest GOVERNMENT SURVEY BY	LUCIUS LYON, D.S.	IN FEBRUARI, 1025 AND
TWO WITNESSES RECORDE	ED:		
W.O. 16 N44W 34 (22.4')			
W.O. 18 S66E 161 (106.3	•)		
CONTINUED ON BACK			
	Dritotees di boilgee bedte - velt t t	or reestablishing corner:	
·	ound and/or method applied in restoring		
A A A A A A A A A A A A A A A A A A A	LOCATION OF CORNER ON	APRIL 3, 1997 AND F	OUND 2" BAR IN
BELOW STONE AND PIPE	ACCEPTED FIRE CLAY AS	PERPENDATION OF	CORNER. REPLACED FIRE
CLAY WITH 4" DIAMETER	CAST IRON MONUMENT AN	D CAP.	
			
- Description of monument for core	ner and accessories established to perpe	tuate locating the position of t	he corner:
J-5 T1S R2W	LONG CAST IRON HARRISON	MONUMENT AND C	AP STAMPED LS 25837
# INCH DIAMETER BY 30	26.67' SUR'	VEY MARKER SIGN P	OST
ESS NAZ	WOOD DOST 26 40' NAII	& TAG #25837 IN TO	P
■85° NAZ 6" SQUARE 241° NAZ 12" WALNUT	61 44' NAIL	& TAG #28409 IN NO	RTH SIDE
241° NAZ 12" WALNUT	92.38' NAIL	. & TAG #28409 IN NO	RTH SIDE * CUSTORE TO
256° NAZ 14" WALNUT	126-50' NAIL	& TAG #28409 IN NO	RTH SIDE
263° NAZ 15" WALNUT		. & TAG #28409 IN NO	RTH SIU SURVEYOR
		ALA MATERIA	NO. 18
HOTE: NAZ IS MAGNETIC	AZIMUTH MEASURED FROM	NORTH.	25837.
0.00	Alas C		26, 1997
-gried by	25837		AND THE PERSON OF THE PERSON O
_rveyor's Michigan License No	20031	- 	