APPROVED LAND CORNER P.A. 3#5 of 1990 //	A NW CORNER, SECTION 3, E	LII	er 1501 page 805		
Chairman Com Lathons			•		
Date Oc7, 30,1995	LAND CORNER RECORDAT Filing Requirement of Act 7		STATE OF NICHIGAN JACKSON COUNTY		
For corners in	-		RECORDED		
Jackson (County)	Located In: Corner Cod	de <i>≠</i> ≠	28 DEC 95 11:19 A.M.		
	T 2S R 1W G-1 T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R T R R	ATIOI ;	GERALD J. McDEVITT REGISTER OF DEEDS of Deeds Stamp & File Number		
	PlatCOMMISSIO		в С D E F G H I J K L M		
in lines 1 and 2 above were in conforma current manual of survey instructions of the Management or by a decree of a Court of Labove were in conformance with the rules Court of Law; established, re-establish expressed below: NOTE: Not more than 4 corners, all on this certificate.	of P.A. 74, Michigan P.A. of 1970, the corner ince with regulations and rules therefore the United States Department of the Interior awand/or that the corner points mentioned of the Michigan Board of Land Surveyors ared, monumented, re-monumented, record in the same town and range, may be	as required in the or, Bureau of Land of in lines 3, 4 and 5 or by a Decree of a overed, found as 10 -3 te recorded 11 12 -3	6 5 4 3 2 1 1 1 1 2 1 1 1 1 2 1 1 1 1 2 1 1 1 1 1 2 1 1 1 1 1 1 2 1		
A. Description of original monument and accessories and/or subsequent restoration: HERVEY PARKE 79.98 INTERSECTED NORTH BOUNDARY 62 LINKS EAST MARCH 6, 1825 OF POST. SET A POST CORNER, SECTIONS 3 £ 4. Y. OAK 12, S77½°W, 26 LINKS; Y. OAK 14, S72½°E, 30 LINKS JOHN HOLCROFT FOUND STAKE AT CORNER AND WITNESSES BY H.F. BEAN NOV. 12, 1886 W. OAK 18, S52°W, 46½ LINKS; W. OAK 14, N89 3/4°W, 39 LINKS					
CONTINUED ON BACK	ORE 10, 532 H, 404 LINES;	\$ 2.00	REMONUMENTATION		
4		\$ 9.00	CORNER REMONUMENTATION		
B. Description of corner evidence for	ound and/or method applied in restori	ng or reestablishing corner:			
ON NORTH DOWN 0.6' B	Y WITH 1/2" REROD AND CAP : ELOW GROUND AND AGREES WITH THFUL PERPETUATION OF THE 1 NTY MONUMENT 0.85' SOUTH ON P LINE).	H ENGER WITNESSES. POSITION OF THE ORIG	ACCEPTED FIRECLAY SINAL CORNER. SET		
•	er and accessories established to pe	· ·			
STAMPED "G-1 T2S RIW S80°E 20d NAIL & S50°E 20d NAIL & S10°E FOUND NAIL S40°W 20d NAIL & S45°W FOUND NAIL N88°W 20d NAIL &	LS NO. 35998". SHINER ON NORTH SIDE OF 12 SHINER ON SOUTH SIDE OF 12 & TAG #25837 IN WEST SIDE SHINER ON NW SIDE OF 20" M IN NW SIDE OF 15" BLACK CH SHINER IN NORTH SIDE OF 30 R1W, JACKSON COUNTY MONUME	* ASH 2 * RED OAK 3 OF 8* SASSAFRAS 2 APLE 5 ERRY 2 * OAK 2	4.65. 5.47. 5.94. 8.23. PROFESSIONAL NO. 35998 0.42. 0.85.		

35998 Signed by _ Surveyor's Michigan License No. FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAM.. 1983

11/09/95

CONTINUED ON BACK

G-1, T2S, R1W

JACKSON COUNTY ROAD COMMISSION HAS WITNESSES FROM THE MICHIGAN STATE HIGHWAY DEPARTMENT FROM 1954.

CLAY TILE CORNER

8" CHERRY N60°W 24.38 7" MAPLE s45°W 31.06 17" OAK S10°W 39.70 7" ELM S10°E 21.18

RONALD L. ENGER, LS #28409

LCRC - L. 4, P. 134 NOV. 4, 1988

FOUND FIRECLAY AT FALLING DISTANCE FROM G-13, T1s, R1W.

SET 1/2" REBAR WITH CAP #25837 ON THE NORTH SIDE OF THE FIRECLAY.

20" OAK WEST (26.3'

10" CHERRY SW 22.08

7" SASSAFRAS S10°E 26.75

FIRECLAY POST (G13, T1s, RIW) WEST 40.4

FIRECLAY POST IS 0.8' NORTH OF THE STANDARD TOWNSHIP LINE.

c.	FIRECLAY S80°E	WITH 1/2" REROD AND CAP #25837 ON NORTH SIDE.		
	S50°E	20d NAIL & SHINER IN NORTH SIDE OF 12" ASH 20d NAIL & SHINER IN SOUTH SIDE OF 12" RED OAK	24.96	
	S10°E	FOUND NAIL & TAG #25837 IN WEST SIDE OF 8" SASSAFRAS	36.10	
	SOUTH	AMENDED CORNER, JACKSON COUNTY MONUMENT	26.76· 0.85·	(ENGER)
	S40°W S45°W	20d NAIL & SHINER IN NW SIDE OF 20" MAPLE	58.85	
	N89°W	FOUND NAIL IN NW SIDE OF 15" BLACK CHERRY 20d NAIL & SHINER IN NORTH SIDE OF 30" OAK		(ENGER)
	West	G-13, T1s, R1w, JACKSON COUNTY MONUMENT		(ENGER)
			40.42'	