												_	
								SURVEY & REMONUMENTATION					
Chairman Southeast Corner of Section 22, Napoleon Township LAND CORNER RECORDATION CERTIFICATE JAN 2 7 1999													
Date Ser. 9, 1998 LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970													
Force	mers in		r ming redi	allement of A	ਕ 74, Mich. P.A. 19	70	S	ECT	ON				
Located In: Corner Code #													
1. Pul	1. Public Land Survey T3S R1E 19 2087035 T R Page: 1 of 1 T R 09/10/1990 11:8												
2. Property Controlling S T R Hindy Reilly - Jackson Co. CORREM L-1580 P-51: in Section S T R 3. Miscellaneous S T R													
Property in Sec. ST_R Register of Deeds Stamp & File Numb 4. Lot No, Recorded Plat											lumbe	r	
5. Private Claims							A B	C D	E F	G H	J	L	
						2	6	5	4	3	2	1	
1, <u>David E. Erickson</u> , in a field survey on <u>February 19</u> 19 <u>97</u> . do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in tines 1 and 2 above were in conformance with requirements.						3 4 5	7	8	. 9	10	11	12	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Record of Joints mentioned in lines 3, 4 and 5						6	18	17	16	15	14	13	
above we	re in conformance wit	th the rules of the A	Michigan Boom	or points mentions	ed in lines 3, 4 and 5	7 8	19	20	21	22	23	24	
Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below. NOTE: Not more than 4 corners, all in the same town and range, may be recorded							30	29	28	27	26	25	
on this certificate.						13		:	-	27	20		
A. De	scription of origina	il monument and	d accessories	and/or subsequ	ent restoration:	12 13	31	32	33	34	35	36	
Around 1825, H. Parke - Deputy Surveyor, Set "Post Cor Secs. 22, 23, 26 & 27" and recorded two witnesses: "Y. Oak 18, S55°W, 41" (27.06') and "W. Oak 12, N88°E, 202" (133.32'). Around 1888, H.F. Bean reported "Found stake at corner. Set by A.H. Delameter agreeing with remains of 1rst Gov't witness"													
(32.58').													
A corner index card of Jackson County Road Commission (JCRC) dated 1946, indicates the corner as "Fireclay post" and list 3 witnesses: "10" Hick., N85°W, 45.10; 14" Hickory, S40°E, 29.40; 10" Hick., N46°E, 32.56". "On south side of corner post, fences are North, South and West".													
In 1995, G.A. Fauser - RLS #18657, reports the corner as "Fnd. Fireclay at fnc. intx." and lists 4 witnesses: "West, 1.50', R.R. fnc. post; S80°E, 7.25', 38" Oak; South 18.35' 10" Oak; North,. 19.78', 38" Oak" per Certificate of Survey (COS) dated 10-30-95.													
Not recorded under P.A. 74.													
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:													
Found top 14" of Fire Clay (FC) with 1" pipe on South side, on South side of fence corner post, fences are North, South and West. Did not find bottom of FC. Did find pieces of sandstone. Accepted found portion of FC as a careful and faithful perpetuation of the original corner. Replaced FC with a standard concrete monument. Buried FC on South side and 1" pipe on North side of monument.													
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:													
Set a 4" diameter x 36" long concrete monument with cap stamped "1997, I-9, T3S-R1E, LS #29245".													
N 69° W Set nail and tag #29245, South side fence post 1.55° S 56° W Set nail and tag #29245, Northwest side 5° Cek 8.55°							اد. اد	للتنفيضان	Militar.				
0.55							Jeries S	E OF	MICHI	N. L.			
N 54° E N 27° E	Set nail and to Set nail and to	ag #29245, Sout ag #29245, Sout	theast side 20	" Hickory	33.15'	Š	8 65°.	PO 41 P		11	<u>.</u>		
North	County Surve	yor sign post	veet olde 21	VER	19.54' 1.0'	Tabula.	* .	DAVII ERICK	SON	* * *			
N 54° E Set nail and tag #29245, Southeast side 20" Hickory 33.15' N 27° E Set nail and tag #29245, Southeast side 20" Oak 19.54' North County Surveyor sign post 1.0' NOTE: Bearings are magnetic Set nail and tag #29245, Southeast side 20" Oak 19.54' 1.0' Land Surveyor No. 29245 LAND SULLAND SULLAN													
		. (·	TANKE OF	D LAN	id sul	A PROPERTY OF			

Surveyor's Michigan License No.

29245

OPM APPROVED BY MICHIGAN STATE BOARD OF LAND SUPVEYORS, JAN. 38, 1971
PIEVASE
PROVED BY MICHIGAN STATE BOARD OF LAND SUPVEYORS, JAN. 38, 1971

REVISED JAN., 1981 ADAPTED FOR WORD PROCESSING MARCH, 1885