JACKSON COUNTY		
APPROVED LAND CORNER P.A. 345 of 1990	New 1/4 Comment Continued Transfer	#2023699
hairman Nean Sulfaine	_North 1/4 Corner of Section 1, Leoni 7	. FIGS. 1204 Lase 712
Date Dec 26, 1996	LAND CORNER RECORDATION CERT	Terkean Co Mī
	Filing Requirement of Act 74, Mich. P	A. 1970 Recorded
For corners in		12/27/96 01:30P
JACKSON Located In	n: Corner Code #	Jerry McDevitt Register of D <b>ee</b> ds
1. Public Land Survey T35	8_R1EL-1	Manage of product
<u> </u>	R	
<del>'</del>		
2. Property Controlling ST_	R	
in Section S T 3. Miscellaneous S T	R	
Property in Sec. ST_	R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	<u></u>	_A B C D E F G H I J K L_M
5. Private Claims		— • • • • • • • • • • • • • • • • • • •
		2 6 5 4 3 2 1
		4 7 8 9 10 11 12
I, <u>David E. Erickson</u> , in a field survey do hereby certify that under requirements of P.	on <u>March 1</u> , 19 <u>96</u> , A. 74, Michigan P.A. of 1970, the corner points mentioned	
in lines 1 and 2 above were in conforman	i lines 1 and 2 above were in conformance with regulations and rules therefore as required in the	
Management or by a decree of a Court of Law	onlied States Department of the interior, Bureau of Lanc and/or that the corner points mentioned in lines 3, 4 and 5 he Michigan Board of Land Surveyors or by a Decree of a	71
Court of Law; established, re-established	ne Michigan Board of Land Surveyors of by a Decree of a , monumented, re-monumented, recovered, found as	8 19 20 21 22 23 24
expressed below:		10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in on this certificate.	the same town and range, may be recorded	n l
A Description of original manufacture	-t and accessing and/or subscribe rectaration	12 31 32 33 34 35 36
A. Description of original monume	nt and accessories and/or subsequent restoration	on: 13 :
Corner not established in original	government survey of 1825, nor subsequent	ly by Bean in 1888.
A Survey by William Worth, LLS # but does give the distance Easterly		orner. He gives no description or witnesses,
This corner has not been recorded	under PA 74 of 1970.	
B. Description of corner evidence f	ound and/or method applied in restoring or rees	stablishing corner:
corners K-1 and M-1, and 2635.16' is 2.94' West of the midpoint.  Reje	West of M-1. I believe this is the corner Worket this monument for the position of the co	Pipe is 0.58' North of a straight line between rith either found of set. It is nearly on line, but rner, due to the position of found corner L-13, between corners L-13 and M-13 (same as M-1)
	and M-1. Set a 60" long Aluminum Pipe with	
C. Description of monument for co	rner and accessories established to perpetuate	locating the position of the corner
Set a 60" long aluminum pipe with	Jackson County Standard Aluminum Cap st	amped "LS #29245, L-1, T3S-R1E, 1996".
S51°W Set nail & tag #2924	5, Northwest side 30" Oak	358.22'
S63°W Set nail & tag #29245	5, North side 12" Maple	146.52'
	5, in top of Gate Post on East Side of Farm F 5, East side 14" Oak on East Side of Farm Ro	Road 217.88' or CF 100.00
	5, East side 14" Oak on East Side of Farm Ro 5, East side 14" Oak on East Side of Farm Ro	pad 185.88' CF MICA
S15°E County Surveyor sig	n post	TO A TO THE PARTY OF THE PARTY
S89°06'44"W    Corner "L-13, T2S-R N23°49'16"W   Found 3/4"  Pinched		26.31' ERICKSON
Westerly Corner "K-1", JCSM		2632.22 Land Surveyor
N89°06'44"E Corner "M-1", JCSM		2632.22' No. 29245
NOTE: Above bearings are not ma	gnetic, and are assumed.	LAND SUR
		LAND 5
$\bigcap$ $\bigcap$ $\bigcap$ $\bigcap$	0 :	
sind the	inton Date 12-2	4-96
Signed by James C. C.	Date 12-2	

29245

Surveyor's Michigan License No. \_\_\_