JACKSON COUNTY APPROVED LAND CORNER SHEVEY & of 1990 East 1/4 Corner of Section 13, Leoni Township EMONUMENTATION LAND CORNER RECORDATION CERTIFICATE Date Jeff JAN 27 1999 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in **JACKSON** Located in: Comer Code # SECTION 2087039 1. Public Land Survey T35 RIE M-6 Page: 1 of : 09/10/1998 11 1.-1580 P-5 2. Property Controlling in Section 3. Miscellaneous Property in Sec. Register of Deeds Stamp & File Number 4. Lot No. , Recorded Plat 5. Private Claims В C D Ē F G н J ĸ L 1 2 6 5 4 3 9 3 1. David E, Erickson in a field survey on April 17 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 đ 7 8 Q 10 11 5 Ġ 18 17 15 16 14 13 7 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below: 8 19 20 2] 22 23 24 9 10 NOTE: Not more than 4 corners, all in the same town and range, may be recorded 30 29 28 27 26 25 on this certificate. 11 12 31 32 33 34 35 -36 Description of original monument and accessories and/or subsequent restoration: Around 1825, H. Parke - Deputy Surveyor, recorded "Qr. Sec. Cor. falls in pond & could set no post". Between 1886 and 1888, H.F. Bean reported "Established this corner. This Post was not set by U.S. Survey" and recorded two witnesses: "Willow 6, N57 1/4°W, 82" (54.12') and "W. Oak 3, North, 232 3/4" (153.62'). Consumers Power Company (CPCo) records dated 12/5/80 note: "Found crockery - remains of wood stake. Set' ground rod." Corner not recorded under Public Act 74. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found ground rod, crockery and remains of wooden stake. Accepted found ground rod and crockery as a careful and faithful perpetuation of the corner as established in the 1880's. Set a standard 4' aluminum rod on the East side of ground rod leaning over the top. Corner is about 7' South into a small pond, in line with fence North. Description of monument for comer and accessories established to perpetuate locating the position of the comer: Set 4' aluminum rod with Jackson County standard aluminum cap stamped "M-6, T3S-R1E, 1997, LS #29245". Set nail and tag #29245, South side 17" Black Cherry N 85° W 86.37 OF MICHIGAN N 67° W Set nail and tag #29245, South side 17" Black Cherry 77.43 N 45° W Set nall and tag #29245, West side 6" Elm 39.58 M 080 M Set nail and tag #29245, West side 4" Elm 33.60 South **County Surveyor sign post** 1.0 *** DAVID F Fire Clay at M-5 North 2664.53 ERICKSON Land Surveyor NOTE: Bearings are magnetic. SEO LAND SURVE Signed by

Surveyor's Michigan License No.

29245

1

12