JACKSOM COUNTY
APPROVED LAND CORNER
P.A. 345 of 1990
Poting
Chairman
Date Nav. 18, 1998

SOUTH # POST, SECTION 33 NORVELL TOWNSHIP

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Fo	or corners in	riinig nequin	ement of Act 74, mich. F.A. 1	370	
J	ACKSON	Located In:	Corner Code ##		
	[County]		Comer Code		
		T 3 S R 2 E	F-13		
1.	Public Land Survey				
		Ŧ R T R			2099411
					Page: 1 of 2 12/23/1998 11:22A
2	Property Controlling	T R S T R			L-1589 P-643
۲.	in Section	S T R	Mindy Reilly - Jap	okson Co. CORREM	F-1000  040
3	Miscellaneous	S T R		Davista, of Davida Ctaura	• Pite Northern
٧.	Property in Sec.	S T R		Register of Deeds Stamp	A Fije Number
			· · · · · · · · · · · · · · · · · · ·		
4.	Lot No, I	Recorded Plat			<b>вні</b> ЈК L M
5.	Private Claims				
				2 - 6 5 4 -	╂╾┇═╂╌┇═╂═┆═┤
				3 - 1 - 1 - 1 - 1 - 1	<del>▐▗</del> ╇ <del>┈╄╼╋╺┪</del> ┉┨
	Dean R. Gutekunst	Sent	tember 25. 97	<b>╺</b> ┡─┤─ <del></del> ──┢┈┢┈	
* t -		, in a field survey onSept	, 19 ,	5	+
			of 1970, the corner points mentioned id rules therefore as required in the		15-14-13-1
III CSS	lines I and Z above were i	ructions of the United States Depart	tment of the Interior, Bureau of Land	7	
Ma	anagement or by a decree of	a Court of Law and/or that the corns	er points mentioned in lines 3, 4 and 5	8 10 20 21	22 23 24
ab	ove were in conformance w	ith the rules of the Michigan Board o	of Land Surveyors or by a Decree of a		
	ourt of Law; established, pressed below:	re-established, monumented, re-	monumented, recovered, found as	10 30 30 30	
	•			11	
M	on this certificate	corners, all in the same town at	nd range, may be recorded	12 31 32 33	
	on this certificate	•		13 3 32 33	34 35 36
A.	Description of original	monument and accessories and	d/or subsequent restoration:	131-1-1-1-1-1	<del></del>
	Original Govern W. Oak 10" B. Oak 10"	nment Post set by Herve N 27 E 4½ links S 46 E 4 links	ey Parke, Deputy Survey	or, 1824.	
	*W. Oak 10 B. Oak 36 Perpetuation b Found firec Continued on b	" S 81 W $175\frac{1}{4}$ lind y Richard E. Gutekunst lay from one witness (ack,	, RLS #7863, April 1970 *) above and set iron p	corner found.	DEAN R GUTEKUNST
В.			applied in restoring or reestablis		
	Found fireclay	3.3' below surface and	d iron in monument box	at surface.	
	Found fireclay 3.3' below surface and iron in monument box at surface.  Corner is approximately on center line of Sharon Valley Road (blacktop) and approximately 8' West of a fence running North.				
	Accepted the fireclay as a careful and faithful perpetuation of the position of the original corner, as remonumented by H. F. Bean.				
	Set a Standard beside monumen		nt on top of the firecl	lay and left iron b	uried
C.	Description of monum	ent for corner and accessories	established to perpetuate location	ng the position of the com	er;
	<u>F-13</u> T3S, R2		iameter X 30" Cast Iron d IS 18658, which is a		
	S 63½ E 46" Oak 70,75' Pole barn spike and washer on South side.  S 45 W Northwest corner concrete foundation barn 147.69'  N 78½ E 3-24" Oak 123.18' Pole barn spike and washer on South side.				
	East North North Steel	line of a 2" Steel cont Post of Section 4, The post and survey marker over monument/by Jack	4S, R2E (Harrison mo	31.9*	
	$\mathcal{L}$	A Nil -	4	_	
Si	gned by	an (Tulepino	Date No	ovember 1, 1998	
	urveyor's Michigan Licen	se No18658	Fod	m approved by Michigan State Woard O	F LAND SURVEYORS, JAN. 28, 1971 REHISED MAY 18, 1975 REVISED JAN., 1983

## Continued,

A.) Southeasterly Northwest corner foundation house #11523 136.85° S 26 W Northeast corner concrete foundation barm 125.90' S 80 W 24" Oak 240.38' \*\* S 65 E 36" Oak 71.70'

243.54' West of the North # Post of Section 4, Town 4 South, Range 2 East

- Not recorded in P.A. 74.

y Reilly - Jackson Co. COR

2099411 Page: 2 of 2 12/23/1998 11:228 L-1589 P-843

.

.