JACKSON COUNTY SOUTHWEST CORNER SECTION 11 APPROVED LAND CORNER GRASS LAKE TOWNSHIP P.A. 345 of 1990	~
Acrine. III	
Chairman LAND CORNER RECORDATION CERTIFICATE	
Date <u>02-12-97</u> Filing Requirement of Act 74, Mich. P.A. 1970 For corners in	
JACKSON Located In: Corner Code ≠ SURVEY & #2028013 1. Public Land Survey T 3 S R 2 E T - 5 REMONUMENTATION Liber 1537 Page Page 1 of 2 Jackson Co., MI T R R R R R R R R R R R R R R R R R R R	
02/21/3/ 08:40	ì
2 Property Controlling S T P	_ 4_
in Section S T R	<u> 105</u>
3. Miscellaneous S T R Register of Deeds Stamp & File Number	ēΓ
Property in Sec. S T R	
4. Lot No , Recorded Plat A B C D E F G H I J K	
5. Private Claims	Ė
Dean R. Gutekunst, in a field survey on 7/27/94 & 11/21/95 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	13-24-
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	—29— —36—
A. Description of original monument and accessories and/or subsequent restoration: Original Government Post set by Hervey Parke, Deputy Surveyor, February 1824. White Oak 8" S 10 E 10½ links (6.93') Yellow Oak 20" N 21 E 68 links (44.88')	No.
No perpetuation found for the 1880's.	
Perpetuation by Richard E. Gutekunst, RLS # 7863, dated 3/28/1963.	*
Found iron pipe	
Continued on back,	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	1971
Found iron pipe to gravel surface of Earber Road, 7/27/1994.	
Excavated a 20' X 20' X 4' to 6' deep hole, with a backhoe, centered around iron, but found nothing additional.	
Corner is 3.7' East of blacktop in gravel shoulder of Barber Road, and approximately in line of occupation East.	
Accepted surface iron found, and recorded by Timothy B. VanGieson, as the only perpetuation of the position of the original corner.	
Set a Standard Jackson County Monument to replace the iron and left iron buried beside monument, 11/21/1995.	
\Rightarrow Description of monument for corner and accessories established to perpetuate locating the position of the corner: 1-5 T3S, R2E Corner is a 4" diameter X 36" concrete monument with a $\frac{1}{2}$ " X 36"	
steel rod and an aluminum cap stamped IS 18658, which is the standard monument for Jackson County. N 15° E 23" Maple 131.33' 40d & washer on East side ** N 75° E Southwest corner stone foundation house 55.85'	
East RR tie post 27.7' 40d & washer on South side (Gone January 1997) East Capped iron # 24621 (Timothy B. VanGieson) 33.0' S 30° E Southwest corner concrete foundation house 154.70' * N 75° W 26" Cak 97.92' Found 60d on North side	
N 40° W Southeast corner of Angle iron corner post in concrete 45.87' N 70° W Steel post and survey marker sign attached 40'	
signed by Rean R Stateburn Date February 1, 1997	
Surveyor's Michigan License No. 18658 FORM APPROVED BY MICHIBAN STATE BOARD OF LAND SURVEYORS, JAX. 2 REVISED IAI REVISED IAI	14, 1975