	JACKSON COUNTY APPROVED LAND CORNEL	NORTH # POST SPRING ARBOR			
	P.A. 345 of 1990 Acting Chairman	_್ರ್ಲ್ LAND CORNER	R RECORDATION CERT	TIFICATELIBER 1482 PAGE 638	
	Date 12-30-94		ment of Act 74, Mich. I		
Fo —	JACKSON (County)	Located In:	Corner Code ##	STATE OF MICHIGAN JACKSON COUNTY RECORDED	
1.	Public Land Survey	T <u>3 S R 2 W</u> T R		17 AUG 95 9:56 A.M.	
2.	Property Controlling S			GERALD J. McDEVITT REGISTER OF DEEDS	
	in Section S Miscellaneous S	T R T R		Register of Deeds Stamp & File Number	
	Property in Sec. S	T R		-	
	Lot No, Recorde Private Claims			2 6 5 4 3 2 1 1	
DEAN R. GUTEKUNST in a field survey on October 6 1993 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land					
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:					
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					
A. Description of original monument and accessories and/or subsequent restoration:					
Original Government Post set by Lucius Lyon, Deputy Surveyor, March 1825. S 60½ E Swamp Oak 12" 402 links (265.32') N 75 E White Oak 18" 297 links (196.02') Perpetuation by H. F. Bean, June 1886 Br. Oak 14" S 83 E 356 links (234.96') Y. Oak 20" N 55½ E 322¼ links (212.69') Fireclay Post (3"Dia. x 24")					
Not recorded in P. A. 74					
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found FTRECLAY, 2.3' below gravel surface of Mathews Road, by backhoe excavation of 6' x 6' x 4' deep area. Found a 1" solid bar in June 1966, gone in October 1993, 1.67' East of fireclay. Found a 1" open iron, 5.34' East of fireclay, October 1993. Corner is approximately 2' West of center line of gravel (Hammond Road) and in line of fence occupation West and in line of center line of gravel (Cox Road) East.					
	Accepted FIRECLAY as a careful and faithful perpetuation of the position of the original corner, as remonumented by Bean in 1886. Replaced fireclay with a Standard Jackson County Monument and left bottom part of fireclay buried under monument.				
C.	D-9 T3S, R2W N 11° W 8" mapl N 12° E 20" Walr N 84° E 20" Cak S 77° E 18" Oak N 51° E 15" Oak	Corner is a 4" steel rod and a standard monume le 126.63' nut 194.25' 155.75' 132.41' 58.30'	diameter X 36" cor in aluminum cap sta ent for Jackson Cou 40d & washer or 40d & washer or 40d & washer or 40d & washer or	East side West side South side North side West side	
		MAN	\mathcal{A}	LAND MANNET	
Sic	gned by	Lakemo	Date	December 29, 1994	
Surveyor's Michigan License No					