Chairman New Chitherna EAST 1/4 POST, SECTION	N 21, SPRING ARBOR TOWNSHIP	
Filing Requirement	CORDATION CERTIFICATE at of Act 74, Mich. P.A. 1970	
For corners in	#2016894	
	er Code # Liber 1529 Page Fage 1 of 1	316
(County)	Jackson Co., MI	
1. Public Land Survey	G-8 Recorded	
' \ T R	10/14/98 09:00A G.J. McDevitt	
T R 2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property In Sec. S T R	Register of Dee	
A Locality Description Disa		iber
4. Lot No, Recorded Plat	ABCDEFGHIJR	L
	2 6 5 4 3 2	- 1 -
	3	_
I. Michael A. Groat , in a field survey on <u>September 12</u> 19 requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in	9 96 do hereby state that under	12-
conformance with regulations and rules therefore as required in the current manu-	nual of survey instructions of the 5	+
United States Department of the Interior, Bureau of Land Management or by a dethat the corner points mentioned in lines 3, 4 and 5 above were in conformance	ce with the rules of the Michigan	-13-
Board of Land Surveyors or by a Decree of a Court of Law, established, recovered, found as expressed below:	I, re-established, monumented,	-24-
NOTE: Not more than 2 corners, all in the same town and range, ma	new he recorded	1
on this certificate.	10 30 29 28 27 26	 25-
	11	+
	12 31 32 33 35	-36-
A. Description of original monument and accessories and/or subse	sequent restoration:	
Original survey, 1825, Lucius Lyon, Deputy Surveyor, set post, I links, Br. Oak, 8", S 11°E, 47 links	hickory, 9" S 64 ½° W, 39	
H.F. Bean, June 12, 1866, found original post and one witness s N 10° W, 47 links	standing, set fireclay post, W. Oak, 24" s 2 ½ $^{\circ}$ E, 89 links, W. Oak, 2	4",
F.A. Fisher, RLS # 3102, Found fireclay at intersection of stone 30.85'; 12" B. Oak, S 85° E, 42.28'; 5" Oak, S 5° E, 23.37; 5" B		
Richard E. Gutekunst, RLS #7863, In L.C.R.C. dated February 1 Set capped iron at NWC of fireclay. Westerly, 14" Oak, 5.07", So Southeasterly, 9" Oak, 11.54', Northerly, 30" Oak, 48.6", Souther	outh Southwesterly 9" Oak, 5.72"; East	
B. Description of corner evidence found and/or method applied in	n restoring or reestablishing corner:	
Found capped iron, RLS# 7863, on NW side of fireclay. Stone fer verified the Gutekunst witnesses from 1976 mentioned in part "A" of the original corner. Set standard Jackson County Monument in of the monument	ence running South. Also found and A". Accepted the fireclay as a careful and faithful perpetuation in place of the fireclay and buried the fireclay and iron on the South sic	le
C. Description of monument for corner and accessories established	ed to perpetuate locating the position of the corner:	
4" x 36" Concrete monument with Jackson County cap stamped	d "G-8, T 3 S, R 2 W, P.S. # 39079", placed survey marker sign 1' Nor	th
Witnesses: N 85° W, Nail In Northerly Side Of 20" Oak, 5.74' South, Nail In Westerly Side Of 24" Oak, 22.84' S 20° W, Nail In Westerly Side OF 15" Oak, 5.9' S 80° W, Nail In Southerly Side Of 15" Oak, 11.11'		
Signed by Michael a. Live	Date 9-30-96	
Michael A. Groat	and the same of th	-
Surveyor's Michigan License No. 39079	form approved by Michigan State Board of Professional Surveyors, Jan. :	28, 19 7
#Groat land Surviving	revised may revised ja revised oc	N., 151
Mor=hall, Dir. 49068		

JACKSON COUNTY APPROVED LAND CORNER