JACKSON COUNTY PPROVED LAND CORNER SECTION 36 SOUTHWEST CORNER. of 1990 P.A. 343 COLUMBIA TOWNSHIP eirman #2040569 LAND CORNER RECORDATION CERTIFICATE Date Liber 1546 Page 465 Filing Requirement of Act 74, Mich. P.A. 1970 Page 1 of 2 For corners in Jackson Co., MI **JACKSON** Located In: Corner Code ## Recorded SURVEY & 07/09/97 01:16P K-13 REMONUMENTATION Mindy Reilly T45 R 1E 1. Public Land Survey Register of Deeds APR 07 1998 T R 2. Property Controlling R SECTION _ T _ R in Section S Miscellaneous S . T. _ R _ Register of Deeds Stamp & File Number R Property in Sec. S Т _ , Recorded Plat . 5. Private Claims in a field survey on Sept. 24, 1996 & May 19, 1997 DEAN R. GUTEKUNST do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 10 11 NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. 12 A. Description of original monument and accessories and/or subsequent restoration: Original Government Post set by Benjamin Hough, Deputy Surveyor, 1815. 14 links (9.24') 92 links (60.72') B. Oak 12" N 4차를 W B. Oak 10" S 60 E Perpetuation by H. F. Bean, no date. Stone Corner * Faple 8" S 814 W $214\frac{1}{2}$ links (141.57') Hickory 10" N 62 E 54 links (35.64') Continued on back, 3. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found Stone, with iron on East side and 4.15' West of iron for the Northwest corner of Section 1, T5S, R1E. Stone is 2.3'+long and approximately 12" wide. Backhoe excavation, 9/24/1996, of a 3' X 10' X 5' deep area, did not reveal additional Reset stone, with brick around and old iron on South side, 4 to ravel surface. information. below existing gravel surface. Accepted the Stone as a careful and faithful perpetuation of the position DEAN original corner, as remonumented by Bean. **GUTEKUNST** Set a Standard Jackson County Monument to replace the Stone, 5/19/1997. No. 18658 1442 3. Description of monument for corner and accessories established to perpetuate locating the position of the corners Corner is a 4" diameter X 30" Cast Iron Harrison monument with a T4S. RIE brass cap stamped LS 18658, which is a standard monument for Jackson County. 30 ₩ 15" Oak 68.35' И 40d and washer on Southwest side. 66.08' S 20° W 24" Naple 40d and washer on West side. S 50° W Northwest corner of concrete foundation of House # 12986 134.13' 45°E N Southeast corner of concrete foundation of House # 12901 202.80' 60° E PK nail in a lead plug and "X" cut on top of a large rock 53.85'

Monument box set by Jackson County Road Commission

18658

igned by

urveyor's Michigan License No.

Date July 1, 1997