JACKSON COUNTY ADDROVED LAND CORNER of 1990 Euker P.A. \$45

Date

Lot No.

SCUTH # POST. SECTION 36 COLUMBIA TOWNSHIP

LAND CORNER RECORDATION CERTIFICATE

Filina	Requirement	of	Act	74.	Mich.	P.A.	1970
	i icqui cii cii	•	~~	, 7,	*******	1 173.	

#2040670 ther 1546 Page 466

ΕO	r corners in	342		Liber 1546 Page 466
	JACKSON (County)	Located In:	Corner Code ## SURVEY &	Pase 1 of 2 Jackson Co., MI
1.	Public Land Survey	T 4 S R 1 E	L-13 REMONUMENTATION	64x62x5t 61x11
		T R T R T R	APR 0 7 1998	Mindy Reilly Register of Deeds
2.	Property Controlling in Section	S T R S T R	SECTION	
3.	Miscellaneous Property in Sec.	S T R S T R	Register of D	Peeds Stamp & File Number

5. Private Claims _ Sept. 25, 1996 & May 19, 1997 DEAN R. GUTEKUNST in a field survey on to hereby certify that under requirements of P.A. 74. Michigan P.A. of 1970, the corner points mentioned

_ , Recorded Plat .

n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land fanagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a ourt of Law; established, re-established, monumented, re-monumented, recovered, found as xpressed below:

IOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 12

.. Description of original monument and accessories and/or subsequent restoration:

Original Government Post set by Benjamin Hough, Deputy Surveyor, 1815.

S 18½ E N 3 W Hickory 16" 12 links (7.92) Hickory 11" 15 links (9.90')

Perpetuation by H. F. Bean, no date

N 13½ W N 46½ V 91 links (60.06') Elm 30" 30" 80 links (52.80') Elm

No description.

Continued on back,

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Stone is 4" X 7" X 15" long. Found Blue Stone with iron on North side.

Backhoe excavation, 9/25/1996, of a 3' X 10' X 6' deep area, did not reveal additional Reset stone to T to 4' below existing gravel surface. information.

Corner is 1' North of center line of Taylor Road (blacktop- May 1997).

Accepted the Stone as a careful and faithful perpetuation of the position of the original corner.

Set a Standard Jackson County Monument to replace the stone, Nay 19, 1997.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

L-13	T45 R1	E Corner is	a 4" diame	eter X 30"	Cast Iron	Harrison mon	ument	with a	
		brass cap	stamped LS	: 18658, wi	nich is a	standard monu	ment i	for	
		Jackson Co	unty.					STAF MINIS	5 .
*	S 25°W	10" Hickory	27.85'	40d and	washer on	West side.		E	11.
	N 60 E	12" Hickory	86.00'	40d and	washer on	North side.	30	PEAN TOTAL	1
**	N 45° W	39" Oak	63.65'	40d and	washer on	South side.	E ★!	DEAN 1	14
***	n 60° h	23" Hickory	72.8°'	40d a n d	washer on	South side.	2 · 1	GUTEKUNST	}_
	S 45°E	26" Naple	58.07 <i>'</i>	40d and	washer on	Northeast sid		No. 18658	12
	N 20°E	11" Ash	41.79'	40d and	washer on	East side.	25		1.
	North	Steel post and	survey ma	rker sign	attached	25.00'	14.	Charmers ?	76.60
	Monument	box set by Jack	son County	Road Comm	ission.		**	Sell Tring	","
.		Muta	temt	n	Ju:	ly 1, 1997		**********	

- JUSION 18658 -veyor's Michigan License No.