P.A. 345 of 1990 / East One Quarter Corner of Section 5, Napoleo	on Township
Chairman Man Challen LAND CORNER RECORDATION CERTIFIC	CATE
Filing Requirement of Act 74, Mich. P.A.	1970
For corners in	
JACKSON Located In: Corner Code #	
1. Public Land Survey T 4S R 2E E-2 Mindy Reilly	2095599 Page: 1 ef 1 11/20/1998 03:25p Jackson Co. CORREM L-1586 P-917
2. Property Controlling S T R S S T R Property in Sec. S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat 5. Private Claims	ABCDEFGHIJKLM
·	2 6 5 4 3 2
	3
3. David E. Erickson, in a field survey on December 19 , 19 97	4 7 8 9 10 11 12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the	5 6 16 17 16 15 14 13
current manual of survey instructions of the United States Department of the Interior, Bursau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5	7
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as	8 19 20 21 22 23 24
expressed below:	9 10 30 29 28 27 26 26
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	11 25 27 26 25
A. Description of original monument and accessories and/or subsequent restoration:	12 31 32 33 34 35 36 13
Around 1824, H. Parke - Deputy Surveyor, set a "Post" and recorded two witnesses: "W. Oak 10, N76° W, 33" (21.78") and "do 18, N18° E, 64" (42.24"). In the 1880's, a Remonumentation Surveyor notes: "Found fireclay post Set for Norvell - Correct" and recorded three witnesses: "Elm 15, S82°E, 79 1/2" (52.47"); B. Cherry 14 N2° E, 131 (not marked)" (86.48"); Three trunk Maple (middle of three) S2° W, 472" (311.52").	
In 1976, R. E. Gutekunst, RLS #7863 recorded the corner as "Found fireclay 8" below surface (10/6/71), 1.7' West of North and South fence, in line fence East %" Iron on Southwest side Fireclay near top of Fireclay %" solid Iron on North side of Fireclay to surface" and notes four witnesses: Nelly (13' East of N & S fence) 4" Walnut, 75.10 to center; N45° ± E, 2" Maple, 88.5 to center; S45° ± E, 10" Swp. Oak, 248.9; South, Iron on centerline Austin Road, 602.70' per Land Corner Recordation Certificate (LCRC) recorded in Liber 2, Page 570.	
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:	
Found intact Fire Clay (FC). Also found a $\frac{1}{2}$ " x 1.89' rebar on North and a $\frac{1}{2}$ " x 18 Found places of brick around base of FC. Accepted found FC as a careful and fa Replaced FC with a standard Jackson County Concrete Monument. Burled FC and	aithful perpetuation of the original corner.
C. Description of monument for corner and accessories established to perpetuate local	ting the position of the corner:
Set 4" x 36" long concrete monument with Iron rod and Standard Jackson Count LS #29245".	y Aluminum Cap stamped "E-2, T4S-R2E,
South Set, nall and tag #29245, West Side Fence Post 6.25	
N 13° E Set, nail and tag #29245, West Side 13" Walnut 74.87 N 56° E Set nail and tag #29245, West Side 7" Oak 88.51	ATE OF MICHIGA
S 46° E Set nail and tag #29245, North Side 20" Oak 248.78	DAVID E.
East County Surveyor sign post 1.0' Note: Bearings are Magnetic	ERICKSON 4
	No. 29245 SUPPLY AND S
\mathcal{O} . \mathcal{O} \mathcal{O} \mathcal{O}	LAND SURVEYER
Signed by Daw Curton Date 11-18	3 - 98
Surveyor's Michigan License No. 20245	S BOARS OF LAND SURVEYORS, JAN 26, 1971

JACKEU. . JUNTY