JACKSON COUNT APPROVED LAND CO P.A. 343 of 199 Active	DRNER / NORTH 🗜 POS	•		
Cheirman Cheirman	LAND CORNE	R RECORDATION CER	TIFICATE	
TIMOTHY B. VANGISSON	97	ement of Act 74, Mich.		#2044409
or corners in			SURVEY &	Liber 1549 Page 129
JACKSON (County)	Located In:	Corner Code #RE	MONUMENTATION	Page 1 of 1 Jackson Co., MI
(County)				Recorded
. Public Land Survey	T 48 R 2 E	<u>L-7</u>	APR 0 7 1998	08/15/97 10:49A Mindy Reilly Register of Deeds
	T R T R		SECTION	KEAT2 (SI OI DESCE
. Property Controlling	S T A			
in Section	S T R			
. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds S	tamp & File Number
•				
	ecorded Plat			E F G H I J K'L M
DEAN R. GUTEKUNST	in a field survey on	7 & June 9 97	2 6 5 3 4 7 8 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	9 -10 -11 -12
<ul> <li>⇒ hereby certily that under requires 1 and 2 above were in urrent manual of survey instruitionagement or by a decree of a pove were in conformance with</li> </ul>	uirements of P.A. 74, Michigan P.A. of conformance with regulations and citions of the United States Depart Court of Law and/or that the corned the rules of the Michigan Board of lestablished, monumented, re-minimum.	of 1970, the corner points men d rules therefore as required ment of the Interior, Bureau o r points mentioned in lines 3, 4 I Land Surveyors or by a Decr	ationed 6 18 17 17 18 18 19 19 19 19 19 19 19 19 19 19 19 19 19	21 22 23 24
DTE: Not more than 4 co on this certificate.	rners, all in the same town an	d range, may be recorded	11 12 31 32	-33 -34 -35 -36 -
Description of original m	nonument and accessories and	or subsequent restoratio		<del></del>
Hickory 14" Y. Oak 12" Perpetuation by Butternut 6" * W. Oak 8" ** Hickory 6"	N 77 E 24 links B. F. LaRue, December N 28 3/4 E 70 S $70\frac{1}{2}$ E 127 S $12\frac{1}{2}$ E 59	s (28.38') s (15.84') c 20, 1884. links (46.2')	Intersected N shown by St Po of Section 24, with E & W Se shown by North	& S \frac{1}{4} line as st and Center Post Set by O. Curtis, ction line as west corner of
Not recorded in	P. A 74.			oint set by Curtis
Description of corner evidence found and/or method applied in restoring or reestablishing corner.  9.91 Ch. East of said corner.				
Backhoe excavation of corner position area did not reveal any evidence of corner. Area has been cut to about 6' lower than banks on either side of road.				
Reset corner position from the two above remaining witnesses.				
Corner is 5' South of center line of Horning Road (blacktop).				
Accepted the two	o witness trees as a c corner, as remonument	eareful and faithfued by LaRue in 188	al perpetuation of t 34.	he position
Set a Standard . under monument.	Jackson County Monumer	it to remark corner	Placed broken	blacktop
<u>L-7 T4S, R2</u>	brass cap stampe Jackson County.	iameter X 30" Cast	cating the position of the c Tron Harrison monuments a standard monument	ment with a
	2" Oak 84.49' P	ole barn spike and	washer on Southwest	t side.
** S 15° E 26" Hickory 39.61' Pole barn spike and washer on West side. N 55° W 19" Cherry 81.56' Pole barn spike and washer on Southwest side.				
N 55° W 19" Cherry 81.56' Pole barn spike and washer on Southwest side. N 60° E 20" Walnut 99.80' Pole barn spike and washer on South side.				
	"steel post in concr	ete 40.7' to	nd masher on south a South face.	TOE NIVE
	teel post and survey	•		THE DE WILLIAM
	nset by the Jagkson C			DEAN
	A della	· <del>-//-</del>	Anguet 1 1007	* R. TENINET
-ed by	18658	Date	Mugust 1, 1997	GUIRONS 1
eyor's Michigan License I	No	<del></del> _	FORM APPROVED BY MICHIGAN STATE BOAT	of culticuliverons, and a second
				The shares