							-		_
				P	EMC	SURV MUN	IENT	& Atio	NC
Carrier Ben Re	<u> </u>	Corner of Section 7 Hanover	•		N	AR 1	3 200	10	
1.16 (08, 10, 199)	7 Filing Re	equirement of Act 74, Mich.	P.A. 1970	SECTION					
For corners in	ocated in:	Corner Code #			100		****		
1. Public Land Survey	T <u>4S</u> R <u>2W</u> T R T R	B-5				P.	10447	Of 1 99 10:1	5 1A
Property Controlling S in Section S. Miscellaneous S. Property in Sec. S.	T R R T R R T R R T R R T R R R R T R R R T R R T R R T R R T	Training Relity	~ Jaokson Co. Registe		RREM eds Sta		-1593 -ile Nui		i8
Lot No, Recorded Private Claims	Plat		1	A B C	D E	f G	н і ,	JK	L N
			2	6	- 5	4	3	2	•
1. David E. Erickson, in a field survey on April 23 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the			d 5	7	8	+		1	12
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				19	20		 	-	24
NOTE: Not more than 4 corners, all in the same town and range, may be recorded				30	29	28	27	26	26
on this certificate. A. Description of original r	nonument and access	ories and/or subsequent restorat	11 12 ion: 13	- 31	32	33	34	35	36
In 1825, R. Clark, Jr (16.50') and "do 9, \$6°W		set a "Post" and recorded	two witnes	ses;	"W. O:	ak 11,	N76°F	Ē, 25'	ır
	es three witnesses:	g, found remains of Witness : "Y. Oak 8, S52½°W 78½"							
Page 303, as "Set capp	ped iron at prorate of centerline road	the corner in a Land Corner ed distance between the 3 in and recorded 4 witnesse 15" Ash, 93.10'.	Southwest (Corner	and :	Southe	ast C	orne	r
B Description of corner ev	vidence found and/or n	nethod annited in rectoring or ree	etablichina co	rner:					

Found ½" x 18" rebar with destroyed cap. Excavated area with backhoe. Found a 12" square on bottom x 6" square on top x 26" long stone, upright, 2' below surface, surrounded by brick. Also found intact Fire Clay (FC), 25' South, 21" deep, surrounded by stones. Accepted found stone as a careful and faithful perpetuation of the original corner. Set a standard Jackson County Harrison Cast Iron Monument in place of the stone. Buried stone West of corner, not alongside of it. Place 2 1/2" x 24" rebars alongside of FC. Keller's iron is 0.98' South and 1.06' East of true comer (He did not use correct corner at C-5 to proportion from). Did not reset this fron.

Description of monument for corner and accessories established to perpetuate locating the position of the corner

N10° E Set Nail & Tag #29245 in West side Power Pole 140.34 \$82° € Set Nail & Tag #29245 in North side 30" Oak 259.55 South Set Nail & Tag #29245 in East side 24" Oak 119.90 S79°W Set Nail & Tag #29245 in North side Power Pole 173.80 South County Surveyor sign post 30.0" South Fire Clay 25.0 Centerline gravel Fowler Road South 9.0'

\$88°48'37"E

N88°52'57"W

Set standard Jackson County Harrison Cast Iron Monument stamped "B-5, #29245".

CO LAND SUR Note: Above Bearings are magnetic. Corner C-5, found FireClay and set Harrison monument 2641.47 Comer A-5 as remonumented 2006.48

Signed by Surveyor's Michigan License No. DAVID F.

ERICKSON and Surveyo