	_		-		ETA (#81	ŞĮ	18/1	.	, 1	-
AGENSON COUNTY APPROVED LAND CORNE P.A. 343 of 1990)		Corner of Section	17 Hanover T	ownehin		6 0 a deser a	IUMI R 1 8	, m = 12 42) 4
Data Mail. 10,1999	LAND CO	DRNER RECORD equirement of Ac	ATION CERTIFIC	CATE			ECTI		•	
For corners in JACKSON Lo (County) 1. Public Land Survey	T4S R2W	Corner Code #				CORREM		Page 11/24	8 073 1: 1 o- 1/1999 818 P	Ø2:42P
Property Controlling S_ in Section S_ Miscellaneous S_ Property in Sec. S_	T R T R T R T R T R T R T R T R T R T R		Mindy Reilly - J	Register						-
4. Lot No, Recorded F 5. Private Claims	Plat			2	B C	D E	F G	н ј	J К	L M
David E. Erickson, in a flet do hereby certify that under requirem in lines 1 and 2 above were in comment manual of survey instruction Management or by a decree of a Coughove were in conformance with the	tents of P.A. 74, Michigan conformance with regulal as of the United States I ant of Law and/or that the	P.A. of 1970, the come tions and rules therefore Department of the Interio corner points mentioned	as required in the r, Bureau of Land n lines 3, 4 and 5	4 5 6 7	7 18	8 17 20	9 16	10 15	14-	<u>12</u>
Court of Law; established, re-eq expressed below: NOTE: Not more than 4 come	stablished, monumented	, re-monumented, rec	overed, found as	10	30	29	28	27	26	25
on this certificate. A. Description of original m	nonument and access	sories and/or subse	quent restoration:	12	3)	32	33	34	35	36
Around 1825, R. Clark, Jr and "B. Oak 8, S9 1/2°W, 21		Set qr. Sec. post"	and recorded two	witness	: #₩	/, Oak	13, N5	°W, 12	2" (7.9	2')
in 1866, H.F. Bean reported Rods N." and recorded two	"Post out, found a witnesses: "Hicko	remains of both W ry 12", S73°W, 76"	itnesses & Stump (50.18') and "Map	of sight	tree : 8°W, 4	508 lin 32" (27.	ks We: .72').	st. Se	st Pos	t 2

Undated Information obtained from Gutekunst Surveyors office, Book H1/82 indicates: "Stone at true corner-F.C. North O.K." and list three witnesses: "SEC Fnd Ho. N37*W, 74.15", Maple 26, N71W, 91.65", Maple 18, S25E, 25.40"

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found ½" iron bar. Excavated area with backhoe. Found a 22" long x 7" x 6" oblong stone standing vertically, surrounded by brick and crockery. Top of stone is 2' deep. Hand dug 33' North in lawn area. Did not find Fire Clay. Found a stump Southeast, 25'. Accepted found stone as a careful and faithful perpetuation of the original corner. Set a standard Jackson County Harrison Monument at the location of the found stone. Monument set down 1.8' with a "T-iron" over per Road Commission request. Corner is on small hill top and will likely be cut in future. Stone was buried in hole.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set standard Jackson County Harrison Monument with cap stamped "D-6 #29245".

N 24° E	Set neil and tag #29245, Southeast side 36" Oak	39.02"
S 52° W	Set nail and tag #29245, North side 30" Oak	37.581
N 63° W	Set nail and tag #29245, South side 30" Oak	50.671
N 36° W	Southeast corner House #8536	74.43'
S 62° W	Found 1/2" iron bar (not replaced)	1.761
South	County Surveyor sign post	18.0

NOTE: Bearings are magnetic

