JACKS	ON COUNTY
APPROVE	LAND CORNER
P.A. 2	245 of 1990,
Chairman	- Jane Euron
Davis	E CHICK SOLL

5 Private Claims

SOUTH & POST, HANOVER TOWNSHIP

SECTION 32

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ができます。これで
Liber 1546 Page 462
Page 1 of 2
Jackson Co., MI
Recorded
07/09/97 01:13P
Mindy Reilly
Register of Deeds

#2040666

Fo	r corners in			1 1 0- 81
JACKSON		Located In:	Corner Code ## SURVEY &	Jackson Co., MI
	(County)		REMONUMENTATION	Recorded 07/09/97 01:13P
1.	Public Land Survey	T 4 S R 2 W	D-13 ————————————————————————————————————	Mindy Reilly Register of Deeds
_		T R T R S T R	SECTION	
2.	Property Controlling in Section	S T R		
3.	Miscellaneous Property in Sec.	S T R S T R	Register of Deeds	Stamp & File Number
4.	Lot No	, Recorded Plat	A B C L	) EFGHIJK <sup>°</sup> LM

May 8, 1997 & June 11, 1997 DEAN R. GUTEKUNST in a field survey on . 19 =do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned =n lines 1 and 2 above were in conformance with regulations and rules therefore as required in the ⇒urrent manual of survey instructions of the United States Department of the Interior, Bureau of Land "Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 Bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Dourt of Law; established, re-established, monumented, re-monumented, recovered, found as ⇒xpressed below:

10 11

12

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

⇒. Description of original monument and accessories and/or subsequent restoration: Original Government Post set by Joseph Wampler, Deputy Surveyor, 1823.

W. Cak 9" 17 links (11.22') 52 links (34.32') N 54 E **8**" N 82 W W. Oak

Perpetuation by H. F. Bean, 1886.

S 71 E N = E  $197\frac{1}{2}$  links (130.35')  $189\frac{1}{2}$  links (125.07') W. Oak 20" Y. Oak 24"

Post out, run and measured the line and found remains of witnesses.

GUTEKUNST

No. 1865B

Continued on back,

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found FIRECLAY 12" below surface of Weir Road (gravel). Found Stone on top of fireclay and broken brick around.

18658

Corner is approximately 2' North of center line of gravel.

No occupation North.

∃rveyor's Michigan License No. ..

Approximately 108' West of hedge row South.

Also found cluster of 6  $-\frac{1}{2}$  brick pieces, 5.0' South and 5.8' East.

Accepted FIRECLAY, as a careful and faithful perpetuation of the position of the original corner as remonumented by H. F. Bean in 1886.

Set a Standard Jackson County Monument to replace the fireclay and left fireclay buried on the North side of the monument and the brick pieces under the monument.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

<u>D</u> -	<u>-13</u>		T4S, R2W		tamped L			rison monument wandard monument	
N	50°	W	28" Cak	40.87 5" F	ole barn	spike and	washer on Sout	chwest side.	
N	200	E	14" Walnut	25.88'	5" Fole	barn spike	and washer on	East side.	
N	70°	E	16" Walnut	86.90'	5" Pole	barn spike	and washer or	North side.	
S	800	Ņ	15" Oak	126.27'			and washer or		
N	700	Ų	9" Walnut	92.45'	5" Pole	barn spike	and washer on	North side.	
No	orth		Steel post	and survey ma	rker sign	n attached	25.0'		
i b	·V		Deank	Juliper	naf	Date	July 1	1, 1997	

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN . 1913