	-				`					-
JACK	SON COUNTY		,			e Iome	URV VUM			N
P.A.	345 of 1990	East 1/4	Corner of Section 17, F	lanover Towns	ship	JA	N 2 7	ř 199	9	
Cheirmen	Den Cotu	LANE	CORNER RECORDATION	N CERTIFICATI	Ε					
Date	Sept. 9, 19	<i>98</i> Fili	ng Requirement of Act 74, I	Wich, P.A. 1970		S	ECT	ION		
	mers in ACKSON (County)	Located In:	Comer Code #							
1. Pul	blic Land Survey	T <u>4S</u> R <u>2W</u> T R T R						Page 09/10	7048 s: 1 cf p/1996 580 P:	11:
in 8 3. Mis	operty Controlling Section scellaneous	TR STR STR	Mind	iy Reilly - Jacks	en Co.	CORRE	M			
	operty in Sec.	<u> </u>		Re	gister of [	eeds S	tamp 8	File N	umber	•
4. Lot	: No, Record	ded Plat			, A B	C D	E F	<del>э н</del> -	JK	L
Q. File	Vale Oldinis				2 6	5	4	3	2	
					3		<u> </u>		-	L
_			4 47		4 7	8 -	9	10	11	1
do here	vid E. Erickson in by certify that under re	a field survey on <u>Ja</u> equirements of P.A. 74, M	inuary 6 , 19 <u>97</u> , ichigan P.A. of 1970, the corner po	ints mentioned	5 -	┼	<del> </del>	<del>                                     </del>		$\vdash$
in lines	1 and 2 above we	re in conformance with	regulations and rules therefore as tates Department of the Interior, E	required in the	6 18	17 (	16	15	14	1
Manage	ement or by a decree of	of a Court of Law and/or the	at the corner points mentioned in li	nes 3, 4 and 5	7	+	<del>                                      </del>	<b></b>		
above v Court	vere in conformance w of Law, established	with the rules of the Michig I, re-established, monul	gan Board of Land Surveyors or by mented, re-monumented, recover	y a Decree of a red, found as	8 19	20	23	22	23	2
	ed below:	,			9					Ι.
NOTE:	Not more than 4	corners, all in the same	town and range, may be record	led	10 30	29	28	27	26	_ 2
	on this certificate	<b>2.</b>		•	12 31	32	33	34	35	-
<b>A</b> . [	Description of origin	nal monument and ac	cessories and/or subsequent (	restoration:	13					_`
	25, R. Clark Jr I 0, S43°W, 92" (60		t a "Post" and recorded tw	o witnesses: "V	V. Oak 46	i, N79°E	E, 47" (	31.02')	and "	W.
		·								
In 188	6, H.F. Bean repo	orted "Post and Both 2, N50°E, 77 1/2" (51.	Witnesses standing" and re	ecorded two with	1esses: '	Y. Oak	14, S4 <sup>(</sup>	3 1/2°V	V, 30 1/	14"
(19.50	janu "vv. Uak 22	" 1400.E" LE 11V. (21°	IV p							

Per field notes on file at Gutekunst Surveyor office, J. Gawlak (for F.C. Riley) in 1934 noted: "Fclay OK in E&W Fence, 1.50' W of fence S." and recorded three witnesses: "W. Oak 14, S±, 12.20'; S. Maple 13, S60°±E, 26.28'; Y. Oak 12, E±, 23.85' ".

B. Description of corner evidence found and/or method applied in restoring or reestablishing comer:

Not recorded under Public Act 74.

Found Fire Clay (FC) in ground, leaning to East. Accepted position of FC base as a careful and faithful <u>perpetuation</u> of the original corner position as monumented by Bean. Set a standard concrete monument and buried FC on South side. Monument is up 0.2' and 1.9' West of current fence South.

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer:

Set 4" diameter x 36" long concrete monument with cap stamped "E-6, T4S-R2W, LS #29245, 1-6-97".

S 58° W	Set nail and tag #29245, Southeast side 12" Oak	42.43'
S 89° W	Set nail and tag #29245, South side 22" Oak	63.38'
N 01° E	Set nail and tag #29245, East side 21" Oak	64.03'
N 82° E	Set nail and tag #29245, South side 17" Walnut	95.50'
North	County Surveyor sign post	1.7'



	LANU	A STATE OF THE STA
Signed by Dair Cuckson	Date 9-8-98	
Surveyor's Michigan License No. 29245	FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971	