JACKSON COUNTY	
APPROVED LAND CORNER	
P.A. 343 of 1990 South West Corner of Section 28, Hanover	•
Date Dec. 9.1998 Filing Requirement of Act 74 Mich P. C.	
Filing Requirement of Act 74, Mich. P.A	. 1970
JACKSON Located In: Corner Code #	
1. Public Land Survey	2097722 Page: 1 of 1
2. Property Controlling S T R Mindy Reilly - Jack in Section S T R  3. Miscellaneous S T R	12/09/1998 11:188 L-1588 P-349
Property in Sec. S T R	Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat	ABCDEFGHIJKL
	2 6 5 4 3 2
Podde Sala	3 9 10 11 12
1. <u>David E. Erickson</u> , in a field survey on <u>December 10</u> do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the	5
Current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management of by a decise of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5.	6 18 17 16 15 14 13
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:	8 19 20 21 22 23 24
NOTE: Not more than 4 corners, all in the same town and range, may be recorded	10 30 29 28 27 26 25
on this certificate.	11 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:	13
In 1825, Robert Clark, Jr Deputy Surveyor, set a "Post" and rec N49° E, 74" (48.84') and "W. Oak 7, N 31 ½ ° W, 160" (105.60').	orded two witnesses: "W. Oak 10,
Remonumentation notes, from the late 1880's, report "Stake with Standing." and recorded two witnesses: "W. Oak 22 N 47 % © E 73 °W 159 1/4" (105.10').	Brick around it. Both Witnesses ¼" (48.34') and "W. Oak 18 N 32 ½
Corner not recorded under P.A. #74	
B. Description of corner evidence found and/or method applied in restoring or reestab	lishing corner:
Found 15" long section of Fire Clay (FC) with a ¾" "REG #7863" car on North side. Removed FC and found several pieces of brick around careful and faithful perpetuation of the original corner, as remonun with a standard Jackson County Concrete Monument. Buried monument.	und base. Accepted found FC as a nented in the 1880's. Replaced FC
C. Description of monument for corner and accessories established to perpetuate local	ating the position of the corner:
Set 4" x 36" long concrete monument with iron rod and Standar stamped "E-11, T4S-R2W, LS #29245, 1997".	
N 70° E Set Nail & Tag #29245 in South side 16" Oak N 49° W Set Nail & Tag #29245 in North side 4" Oak S 12° W Set Nail & Tag #29245 in West side 12" Oak S 6° E Set Nail & Tag #29245 in West side Power Pole West County Surveyor sign post Note: Bearings are magnetic.	22.47' 43.00' 60.31' 51.55' Land Surveyor No. 29245  AND SURFERENCE  AND SURFE
Signed by Land Euchsm Date 12-8-0	
Surveyor's Michigan License No. 20245	

REVISED MAY 14, 1975
REVISED JAM., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1983