JACKSON COUNTY	REMONUMENTATION						
P.A. 345 of 1990 South 1/4 Corner of Section 16, Hanover Tow	mahi		IAN	9 mg .	faaa		
Chairman Wilder Chairman LAND CORNER RECORDATION CERTIFICA	-	p «	JEIN	<i>અ</i> (1999		
Date <u>667.9 1998</u> Filing Requirement of Act 74, Mich. P.A. 197			SE(TTC			
For comers in							
1. Public Land Survey T4S R2W F-7 Page: 1 of 1							
2. Property Controlling S T R Mindy Reilly - Jee in Section S T R 3. Miscellaneous S T R Property in Sec. S T R			GOR]] 99 L-	/10/10: - 1580	P-52
Lot No, Recorded Plat Private Claims	Register of Deeds Stamp & File Number						
	1 2			Υ	T T		
	3	6	5	4	3	2	1
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United Courtest.	5	7	8	9	10	1 1	12
Management or by a decree of a Court of Law and/or that the control points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Record of Land	6	18	17	16	15	14	13
Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:	8	19	20	21	22	23	24
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	10 11	30	29	28	27	26	25
A. Description of original monument and accessories and/or subsequent restoration:	12 13	31	3 2	33	34	35	36
Oak 12, N33°E, 45" (29.70'). In 1886, H.F. Bean reported "Stone Post & both Witnesses standing. Set F.C. Post - 2 Rods South of corner" and noted two witnesses: "Hickory 14, N65°W, 100" (66.00") and "Y. Oak 14, S1 1/2°W, 134" (88.44"). A corner index card of Gutekunst Surveyors dated 1964, indicates the corner as "Found Fire Clay 33.0" S, set iron on North side. Set 1/4 post from witnesses, iron." and lists 5 witnesses: "14" Hickory, N20°W, 27.50'; 20" Hickory, S60°E, 73.63'; 12" Hickory, S30°W, 37.80'; Fence Post, South, 34.0'; Fire Clay is 1.0' North of fence." This corner not recorded under PA #74 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.							
Excavated a 1' North-South and 1.5' East-West hole, 4 1/2' deep to sandy soil. Found a 1" pinch pipe 32.90' North of Fire Clay (FC). Accepted the found pinch pipe as the approximate position of the original corner. Set a standard concrete monument 33.00' North of found FC for a careful and faithful perpetuation of the original corner.							
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:							
Set 4" diameter x 36" long concrete monument with cap stamped "F-7, T4S-R2W, LS #29245, 1997".							
N 54° E Set nail and tag #30087, Southeast side 15" tree 50.34' N 06° W Set nail and tag #30087, West side 14" tree 30.29'			الفليندر	Wille.			
S 41° W Set nail and tag #30087, North side 24" Hickory 37.40"		J. W. S.	LE OF	MICA	Market Land		
South County Surveyor sign post 33.0	į	51	•••	•••	1/4		
NOTE: Bearings are magnetic							
Signed by Dail Suikan Date 9-8-98							
Surveyor's Michigan License No. 30087 FORM APPROVED BY MICHGAN STATE BOWLD OF LAND SURVEYORS, AND. 29, 1871							