FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN 28, 1 REVISED MAY 14, 11 REVISED JAN , 11

March 1, 1997

__ Date ___

18658

Surveyor's Michigan License No. ..

K-10 T4S, R2W

A.

- Perpetuation by Richard E. Gutekunst, RIS # 7863, July 1965.
Found stone at corner, set iron on North side.
Stone about 1' below surface.
Found fireclay, East, 24.75'

* S 88 E 30" Double Hickory 43.90' ** S 88 W 60" Oak 15.65'

- Perpetuation by Dean R. Gutekunst, RIS # 18658, January 1972.
Found iron to surface of Reynolds Road (gravel).
Found fireclay and iron, East, 24.75

* S 88 E 30" Double Hickory 44.25'

** S 88 W 60" Oak 17.3' gone 1995(removed in road reconstruction)

S 20 E 13" Hickory 76.51' gone 1995

N 18 W 4" Hickory 49.3' gone 1995

- P.A. 74, recorded by Anthony P. Kurzy, RLS # 14326, dated October 10, 1975, in LCRC, Liber 2, Page 515, Jackson County Records.

3/4" iron pipe in center line of Reynolds Road

** West 60" Oak 18.61'

* East 2-12" Oak 42.45' (Double Hickory)
S 20 W 6" Oak 57.25'
S 15 E 12" Cherry 76.11'

76 - - -