LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

(m) (m) (m) (m)		
	State of the Assessment of the	,

For corners in	1	in	r corners	For
----------------	---	----	-----------	-----

· o. outlides in				helf de f	1 20	11
KALKASKA (County) 1999 REMONUMENTATION 1. Public Land Survey	Located in: T_25N R_7W	Corner Code #		SECT		
2. Property Controlling in Section 3. Miscellaneous Property in Sec. 5. Lot No, Record 5. Private Claims	TR TR TR S TR S TR S TR S TR	Kaikaska County Jo	an Hall, Regis	92 RE	: B P	0169 1 of 1 600 03:40P G: 115
I, EUGENE FARRER that under requirements of P.A. 74 and 2 above were in conformance manual of survey instructions of Management or by a decree of a C and 5 above were in conformance Dacree of a Court of Law; establish below: NOTE: Not more than 2 comers, a on this certificate.	e, with regulations and rules the the United States Department tourt of Law and /or that the cor- with the rules of the Michigan	corner points mentioned in lines 1 erefore as required in the current to fithe Interior, Bureau of Land oner points mentioned in lines 3, 4. Board of Land Surveyors or by a d, recovered, found as expressed	4 - 7 - 8 5 - 18 - 17 7 - 1 - 18 8 - 19 - 20 9 - 10 - 30 - 29 11 - 12 - 31 - 32 13		-10 -15 -22 -27 -34	-11 -12 -13 -14 -13 -23 -24 -15 -15 -15 -15 -15 -15 -15 -15 -15 -15

Description of original monument and accessories and/or subsequent restoration:

G-4: 1/4 Cor. Common to Sec. 9 & 10. T25N-R7W. Garfield Township
1853, G.L.O. Resurvey, by V.W. Caukin (Deputy Surveyor) Co Survey Notes Pg 45, set 1/4 Section post, Beech 12", N32.25°W, 42 Lks; Beech 10",

1901; 1904, Survey, by W.S. Merrill (Co. Surveyor) Co. Survey Bk 11, Pg 84-85, & Bk 25, Pg. 132, no acc.
1989, 1990, 1998, LCRC & Survey, by E. Farrier (Co. Surveyor) found 1" iron pipe with a 3/8" rod riser in c/l N-S road, found nail in power pole,
N44°W, 38.86', nail in 10" Apple, S61°W, 94.65'; nail in 8" R. Pine, S23°E, 68.52'; nail in 6" Apple, S72°E, 54.61'

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-4: 1/4 Cor. Common to Sec. 9 & 10. T25N-R7W, Garfield Township

Found 3/8" X 18" rerod raised over 1" iron pipe in centerline N-S road. Pulled 3/8" rerod and replaced with 5/8" X 18" rerod w/brass cap. 827°E, 68.51', 10" R. Pine, set nail & washer \$20°W, 91.08', 3" X 3" sg. wood post, set neil & washer N50°W, 38.84', power pole, set nail & washer over old nail No G.I. O. witnesses was found.

No G.L.O. witnesses were found.

Chairman 💋

02-03-00 Date .

Description of monument for corner and accessories established to perpetuate locating the position of the corner;

G-4: 1/4 Cor. Common to Sec. 9 & 10. T25N-R7W, Garfield Township

G-4: 1/4 Cor. Common to Sec. 9 & 10. 125N-ft/W. Garrielo Township
Found 3/8" X 18" rerod raised over 1" iron pipe in centerline N-S road. Pulled 3/8" rerod and replaced with 5/8" X 18" rerod w/brass cap.
N65°E, 49.16', 3" R. Pine, set nail & washer
S27°E, 68.51', 10" R. Pine, set nail & washer
S20°W, 91.08', 3" X 3" sq. wood post, set nail & washer

N50°E, 49.15°, 3" N. Pine, set nail & washer
S27°E, 68.51', 10" R. Pine, set nail & washer
S20°W, 91.08', 3" X 3" sq. wood post, set nail & washer
N50°W, 38.84', power pole, set nail & washer over old nail
Kalkaska County Peer Group accepted the above monument as the best available evidence of the position of the original

erEUGENE D. 2455 FARRIER

Signed by Michigan Licenson 10. 2459 24594

Dets 02-04-00

_Surveyor's