

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

MAD C 1 2000

For corners in SECTION <u>KALKASKA</u> Located In: Corner Code # (County) 1999 REMONUMENTATION 1. Public Land Survey T_25N R_7W G-9 R R 2. Property Controlling R in Section R 3020174 Page: 1 of 1 02/04/2000 03:40P REMON 3. Miscellaneous Property in Sec. 4. Lot No. _____, Recorded Plat 5. Private Claims 2 3 5 I. EUGENE FARRIER in a field survey on November 2, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 6 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land 8 Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a 9 Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: 11 NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. Description of original monument and accessories and/or subsequent restoration: G-9: Sec. Cor. Common to Sec. 21, 22, 27. & 28. T25N-R7W. Garfield Township
1853, G.L.O. Resurvey, by V.W. Caukin (Deputy Surveyor) Co. Survey Notes Pg. 41, set post, Beech 6", 39.5°E, 18 Lks (11.88'); Hemlack 10°, 543.75°W, 29 Lks (19.14'); Y. Birch 8", N16°W, 12 Lks (7.92') 1912, Survey, Fargo, found one U.S. witness, Hemlock stump N55°E, 0.755 Ch. (49.83'); Hemlock stump 24" N57.5°W, 107.5 Lks (70.95') 1933, H.L. Betsford, found 3/4" pipe & crockery, L.E.S. cor. post N40°E, 40.4'; W.P. stump, S88°W, 62.2'; set railroad rail 33' East of corner 1981, LCRC, by E. Farrier (Co. Surveyor), recorded in Liber 2, Pg. 305, found 3/4" iron pipe that fit 1933 survey made by Cons. Power, N06°E, 31.55', 2" Pipe (bad corner); N15°E, 82.75', power pole; East, 55.10', 20" Maple; S80°W, 22.22', 8" R. Pine, N34°W, 28.30', 7" Cherry 1982, Consumers Power, D. Ankrom, found Fargo iron & crockery, 2 1/2" pipe, N2°E, 31.6'; 6" Red Pine, S85°W, 22.22'; 12" Maple, N75°E, 55.12'; 6" W. Cherry, N25°W, 28.33' 1984, Survey, by E. Farrier (Co. Surveyor), found 1/2" Iron & Cap # 21265, set by D. Ankrom for Cons. Power Co. (1982) 1988, Survey, by C.L. Robinson, recorded in Liber 3, Pg. 296, found 1/2" iron pipe; 2" iron pipe, NO4°E, 30.82'; 15" Maple, N89°E, 55.18'; 9" R. Pine, N17°E, 59.98'; 6" R. Pine, S81°W, 22.24' OF MICHIGANA Description of corner evidence found and/or method applied in restoring or reestablishing corner: G-9: Sec. Cor. Common to Sec. 21, 22, 27, & 28, T25N-R7W. Garfield Township
Found & accepted 3/4" iron pipe w/ broken crockery 1.5' West of centerline N-S seasonal road 82' +/- S. of OHP. HE OF MICHIGA N15°E, 82.75', power pole, found spike
East, 65.20', 20" Maple, found spike
S50°E, 23.86', 12" Cherry, set nail & washer
S75°W, 22.00', 12" R. Pine, set nail & washer F. ARER Ratified by Peer Group P.A. 345 - 1990 Kalkaska County CESTRIONAL NG6°E, 31.55', 2" pipe unaccepted for corner SUNVEYOR No G.L.O. witnesses were found. No. 24594 -00 Date OFESSION THE OFESSION C. Description of monument for curner and accessories established to perpetuate locating the position of the corner; G-9; Sec. Cor., Common to Sec. 21, 22, 27, & 28, T25N-R7W, Garfield Township Found & accepted 3/4" iron pipe w/ broken crockery 1.5' West of centerline N-S seasonal road 82' +/- S. of OHP. Added 5/8" X 18" rerod w/ bress cap. N15°E, 82.75°, power pole, found spike East, 55.20°, 20" Maple, found spike \$50°E, 23.86', 12" Cherry, set nail & washer \$75°W, 22.00', 12" R. Pine, set nail & washer N06°E, 31.55', 2" pipe unaccepted for corner Kalkaska County Peer Group accepted the above monument as a careful and faithful perpetuation of the position of the original corner. 02-04-00 Signed by Surveyor's

24594