LAND CORNER RECORDATION CERTIFICATE

	Filing Requirement of Act 74,	Mich. PA 1970
For Corners In: Kalkaska (County)	Located In Corner Code #	
1. Public Land Survey	T 26N R 6W L8	
Property Controlling in Section	T R	
Miscellaneous Property in Section	S T R S T R	Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:	T ABCDEFGHIJKLM
5. Private Claims:		_ 2 6 5 4 3 2 4 1
requirements of PA 74, Mic and 2 above were in confo the current manual of sur Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of established, re-established,	field survey on April 14, 2008 do hereby state that under chigan PA of 1970, the corner points mentioned in lines 1 rmance with regulations and rules therefore as required in vey instructions of the United States Department of the inagement or by a decree of a Court of Law and/or that the lines 3, 4 and 5 above were in conformance with the rules f Land Surveyors or by a Decree of a Court of Law; monumented, recovered, found as expressed below: 2 corners, all in the same town and range, may rtificate.	5 6 18 17 16 15 14 13
A. Description of origina	monument and accessories and/or subsequent rest	oration:
Set ½" bar; 1) 4" 0. 3) Tw. Beech N22° - 1975 – LCRC #353 cap at intersection 4) 12" Tw. Beech S 6) 9" Tw. Maple S8	3-A; H. L. Fluharty – Set 5/8" x 18" rerod with RLS of ¼ lines 19.45', N33°E from "Ostling" iron; 340°W 15.77'; 5) 10" Tri. Maple N5° 18.48';	- 2000 – Unrecorded Survey – Farrier Surveying – File No. 0188A – D. R. Farrier – Set ½" rod and cap; 7) #12026 – N40°35′54″W 3.17′; 8) #18223 – N24°16′11″E 20.58′
B. Description of corner	evidence found and/or method applied in restoring o	r re-establishing corner:
S43°15'E 1.62' to f <u>Point 'C'</u> - N36°41'\ that a blunder was 'M8' and is also rej	d. $\frac{1}{2}$ " CIR #24594 – 41098 per 2000 Farrier survey; $\frac{1}{2}$ W 1.55' to calculated position (iron removed) based of made in the establishment of Point 'B' and is thus rejected. Point 'C' is the most historical position for the	the calculated intersection of ¼ lines we find: Point 'A' Point 'B' - N29°05'E 20.03' to Fd. 5/8" CIR #18223 and on 2000 Farrier tie to 1972 Ostling survey iron. It is apparent jected. Point 'A' was based on a rejected position at corner corner and fits the intersection of the ¼ lines best thus set h is accepted as the best available evidence of the position
C. Description of monur	nent for corner and accessories established to perpe	tuate locating the position of the corner:
S83°W 20.40' to se N23°W 11.22' to se S40°02'E 3.17' to f N33°16'E 19.44' to	Cap on 5/8" x 34" rebar N & T in W. side 6" Oak (#1) et N & T in S. side 8" S. Maple (#2) et N & T in W. side Tw. 12" Beech (#3) fd. 1/2" CIR #24594 – 41098 (Point 'A') of d. 5/8" CIR #18223 (Point 'B') carsonite Post with loc. Tag	CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088
Signed by:	one or naven	ate: 11/23/2009